Dual Measurement Multimeter

GDM-8261A

USER MANUAL

GW INSTEK PART NO. 82DM-8261AEC1

ISO-9001 CERTIFIED MANUFACTURER GW INSTEK

This manual contains proprietary information, which is protected by copyrights. All rights are reserved. No part of this manual may be photocopied, reproduced or translated to another language without prior written consent of Good Will company.

The information in this manual was correct at the time of printing. However, Good Will continues to improve products and reserves the right to change specifications, equipment, and maintenance procedures at any time without notice.

Good Will Instrument Co., Ltd.

No. 7-1, Jhongsing Rd., Tucheng Dist., New Taipei City 236, Taiwan (R.O.C.).

Table of Contents

SAFETY INSTRUCTIONS 6
Safety Symbols 6
Safety Guidelines 7

GETTING STARTED 10
GDM-8261A Characteristics 11
Front Panel Overview 12
Rear Panel Overview 18
Set Up 20

BASIC MEASUREMENT 23
Basic Measurement Overview 25
AC/DC Voltage Measurement 27
AC/DC Current Measurement 32
2W/4W Resistance Measurement 34
Diode Test 37
Continuity Test 38
Frequency/Period Measurement 41
Temperature Measurement 43

DUAL MEASUREMENT 49
Dual Measurement 49

ADVANCED MEASUREMENT 55
Advanced Measurement Overview 56
dBm/dB/W Measurement 58
Max/Min Measurement 61
Relative Value Measurement 62
Hold Measurement 64
Compare Measurement 65
Math Measurement 68

SYSTEM/DISPLAY CONFIGURATION 74
Refresh Rate Setting 75

View Serial Number 75
Trigger Setting 76
Filter Setting 79
Display Setting 83
Measurement Configuration Settings 84
ADC Setting 88
Frequency / Period Settings 93
Identification Settings 96

STORE/RECALL 97

Store Measurement Record 98
Recall Measurement Record 99
Save Instrument Settings 100
Recall Instrument Settings 101

SCANNER (OPTIONAL) 103

GDM-SC1 Scanner Specifications 104
Scanner Installation 104
Setup Scan 113
Run Scan 120

DIGITAL I/O 123

Digital I/O Terminal Configuration 124

REMOTE CONTROL 130

Configure Interface 132
Web Control Interface 159
Command Syntax 163
Command Set 164

FAQ 209

APPENDIX 211

Firmware Version 212
Fuse Replacement 213
Menu Tree 215
Specifications 217
EC Declaration of Conformity 227

INDEX 228

SAFETY INSTRUCTIONS

This chapter contains important safety instructions that you must follow when operating the GDM-8261A and when keeping it in storage. Read the following before any operation to insure your safety and to keep the GDM-8261A in the best possible condition.

Safety Symbols

These safety symbols may appear in this manual or on the GDM-8261A.

WARNING	Warning: Identifies conditions or practices that could result in injury or loss of life.
CAUTION	Caution: Identifies conditions or practices that could result in damage to the GDM-8261A or to other property.
	DANGER High Voltage
	Attention Refer to the Manual
	Protective Conductor Terminal
	Earth (ground) Terminal
	Do not dispose electronic equipment as unsorted municipal waste. Please use a separate collection facility or contact the supplier from which this instrument was purchased.

Safety Guidelines

General Guideline

CAUTION

- Make sure that the voltage input level does not exceed DC1000V/AC750V.
- Make sure the current input level does not exceed 10A.
- Do not place any heavy object on the GDM-8261A.
- Avoid severe impact or rough handling that can lead to damaging the GDM-8261A.
- Do not discharge static electricity to the GDM-8261A.
- Use only mating connectors, not bare wires, for the terminals.
- Do not block or obstruct the cooling fan vent opening.
- Do not perform measurement at the source of a low-voltage installation or at building installations (Note below).
- Do not disassemble the GDM-8261A unless you are qualified as service personnel.
- Make sure that the Sense LO terminal to COM port is limited to 100Vpk, the Sense HI to Sense LO terminals are limited to 200Vpk and the COM port to earth is limited to 500Vpk.

(Note) EN 61010-1:2010 specifies the measurement categories and their requirements as follows. The GDM-8261A falls under category II 600V.

- Measurement category IV is for measurement performed at the source of low-voltage installation.
- Measurement category III is for measurement performed in the building installation.
- Measurement category II is for measurement performed on the circuits directly connected to the low voltage installation.

Power Supply

WARNING

- AC Input voltage: 100/120/220/240 V AC ±10%, 45Hz to 66Hz / 360Hz to 440Hz
- The power supply voltage should not fluctuate more than 10%.
- Connect the protective grounding conductor of the AC power cord to an earth ground, to avoid electrical shock.

Fuse WARNING	• Fuse type: 0.315AT 100/120VAC 0.125AT 220/240 VAC • Make sure the correct type of fuse is installed before power up. • To avoid risk of fire, replace the fuse only with the specified type and rating. • Disconnect the power cord before fuse replacement. • Make sure the cause of a fuse blowout is fixed before fuse replacement.
Cleaning the GDM-8261A	• Disconnect the power cord before cleaning. • Use a soft cloth dampened in a solution of mild detergent and water. Do not spray any liquid into the GDM-8261A. • Do not use chemicals or cleaners containing harsh material such as benzene, toluene, xylene, and acetone.
Operation Environment	• Location: Indoor, no direct sunlight, dust free, almost non-conductive pollution (Note below) • Temperature: Full accuracy for 0°C to 55°C. • Humidity: Full accuracy to 80% RH at 40°C (Note) EN 61010-1:2010 specifies the pollution degrees and their requirements as follows. The GDM-8261A falls under degree 2. Pollution refers to "addition of foreign matter, solid, liquid, or gaseous (ionized gases), that may produce a reduction of dielectric strength or surface resistivity". • Pollution degree 1: No pollution or only dry, non-conductive pollution occurs. The pollution has no influence. • Pollution degree 2: Normally only non-conductive pollution occurs. Occasionally, however, a temporary conductivity caused by condensation must be expected. • Pollution degree 3: Conductive pollution occurs, or dry, non-conductive pollution occurs which becomes conductive due to condensation which is expected. In such conditions, equipment is normally protected against exposure to direct sunlight, precipitation, and full wind pressure, but neither temperature nor humidity is controlled.
Storage Environment	• Location: Indoor • Temperature: −40°C to 70°C
Disposal 	Do not dispose this instrument as unsorted municipal waste. Please use a separate collection facility or contact the supplier from which this instrument was purchased. Please make sure discarded electrical waste is properly recycled to reduce environmental impact.

Power cord for the United Kingdom

When using the GDM-8261A in the United Kingdom, make sure the power cord meets the following safety instructions.

NOTE: This lead / appliance must only be wired by competent persons

WARNING: THIS APPLIANCE MUST BE EARTHED

IMPORTANT: The wires in this lead are coloured in accordance with the following code:

Green/ Yellow:	Earth
Blue:	Neutral
Brown:	Live (Phase)



As the colours of the wires in main leads may not correspond with the coloured marking identified in your plug/appliance, proceed as follows:

The wire which is coloured Green & Yellow must be connected to the Earth terminal marked with either the letter E, the earth symbol ⏚ or coloured Green/Green & Yellow.

The wire which is coloured Blue must be connected to the terminal which is marked with the letter N or coloured Blue or Black.

The wire which is coloured Brown must be connected to the terminal marked with the letter L or P or coloured Brown or Red.

If in doubt, consult the instructions provided with the equipment or contact the supplier.

This cable/appliance should be protected by a suitably rated and approved HBC mains fuse: refer to the rating information on the equipment and/or user instructions for details. As a guide, a cable of 0.75mm^2 should be protected by a 3A or 5A fuse. Larger conductors would normally require 13A types, depending on the connection method used.

Any exposed wiring from a cable, plug or connection that is engaged in a live socket is extremely hazardous. If a cable or plug is deemed hazardous, turn off the mains power and remove the cable, any fuses and fuse assemblies. All hazardous wiring must be immediately destroyed and replaced in accordance to the above standard.

GETTING STARTED

This chapter describes the GDM-8261A in a nutshell, including an Overview of its main features and front / rear panel introduction. After going through the Overview, follow the Power-up sequence to properly setup the GDM-8261A.

Please note the information in this manual was correct at the time of printing. However as GW Instek continues to improve its products, changes can occur at any time without notice. Please see the GW Instek website for the latest information and content.

Characteristics	GDM-8261A Characteristics	11
Panel Overview	Front Panel Overview	12
	Measurement Keys (upper row)	13
	Measurement Keys (lower row)	16
	Rear Panel Overview	18
Setup	Tilt Stand	20
	Power Up	21

GDM-8261A Characteristics

The GDM-8261A is a portable, dual-display digital multimeter suitable for a wide range of applications, such as production testing, research, and field verification.

Performance	• High DCV accuracy: 0.0035% • High current range: 10A • High Voltage range: 1000V • High ACV frequency response: 300kHz
Features	• 6 ½ digits • Multi functions: ACV, DCV, ACI, DCI, 2W/4W R, Hz, Temp, Continuity, Diode test, MAX/MIN, REL, dBm, Hold, MX+B, 1/X, REF%, dB, Compare, Statistics. • Manual or Auto ranging • AC true RMS
Interface	• Voltage/Resistance/Diode/Temperature input • Current input • 4W sense input • USB device/RS232/GPIB(optional)/LAN(optional) for remote control • 9-pin digital I/O • 16 channel scanner (optional)
Optional Items	• 16 channel scanner • GPIB port • Ethernet port

Front Panel Overview



Power Switch



Turns On ▬ or Off ▮ the main power. For the power up sequence, see page 21.

Main Display

Shows measurement results and parameters.

For display configuration details, see page 82 (light setting).

DC/AC 1A Terminal

AMPS Fuse Holder



As a fuse, protects the instrument from over-current. Rating: T1.25A, 250V.(This terminal accepts DC/AC current input)

For the fuse replacement procedure, see page 214.

DC: 100μA~1A

AC:1mA~1A

For details see page 32.

Sense LO Terminal

Accepts LO sense line in 4W resistance measurement. For details, see page 34

Sense HI Terminal		Accepts HI sense line in 4W resistance measurement. For details, see page 34.
Input LO Terminal		Accepts ground (COM) line in all measurements except the sense line in 4W Resistance (page 34). The maximum withstand voltage between this terminal and earth is 500Vpk.
Input HI Terminal		Used as an input port for all measurements except for DC/AC Current measurements.
DC/AC 10A Terminal		Accepts DC/AC Current input. For DCI or ACI details, see page 32.

Measurement Keys (upper row)

SHIFT/EXIT		The Shift key is used to select the secondary functions assigned to each front panel key. When pressed, the **SHIFT** indicator appears in the display. As the Exit key, it gets out of the parameter configuration mode and goes back to the measurement result display mode.
ACV		Measures AC Voltage (page 27).
SHIFT → ACV (SCAN)		Starts the optional scan measurement (page 113).
DCV		Measures DC Voltage (page 27).

SHIFT → DCV (STEP)		Starts the step measurement (page 113) using the optional scanner.
ACI		Measures AC Current (page 32).
SHIFT → ACI (RECALL)		Recalls a normal measurement result, standard deviation measurement readings (page 99) or scan measurement results (page 121).
DCI		Measures DC Current (page 32).
SHIFT → DCI (STORE)		Stores a measurement result (page 98).
2/4W (Resistance)		Measures 2-wire or 4-wire Resistance (page 33).
SHIFT → 2/4W (MATH)		Enters the Math measurement mode (page 68).
→||/•)) (Diode/ Continuity)		Tests Diode (page 37) or Continuity (page 38).
SHIFT → →||/•)) (dBm)		Measures dBm (page 58).
Hz/P (Frequency/ Period)		Measures Frequency or Period (page 41).

SHIFT + Hz/P (dB)		Measures dB (page 59).
TEMP (Temperature)		Measures Temperature (page 43).
SHIFT + TEMP (SENSOR)		Selects the type of thermocouple used in the Temperature measurement (page 44).

Measurement Keys (lower row)

AUTO/ENTER	AUTO ENTER	As the AUTO key, selects the measurement range automatically. As the Enter key, confirms the entered value.
SHIFT → AUTO (RATE)	SHIFT / EXIT → RATE AUTO ENTER	Selects the measurement update rate: Slow, Medium, or Fast (page 25).
Up/Down	▲ ▼ RANGE	Selects the parameter in various occasions: higher (▲) or lower (▼).
HOLD	◀HOLD	Activates the Hold function (page 64).
SHIFT → HOLD (COMPare)	SHIFT / EXIT → COMP ◀HOLD	Activates the Compare measurement (page 65).
TRIG (Trigger)	TRIG▶	Triggers sample acquisition manually (page 76).
SHIFT → TRIG (Int/Ext Trigger)	SHIFT / EXIT → INT/EXT TRIG▶	Selects the Internal or the External trigger source (page 76).
Left/Right	◀HOLD TRIG▶ CHOICES	Selects parameters in various menus: left (◀) or right (▶).
REL	REL	Measures the Relative value (page 62).

SHIFT → REL (RELative base)		Manually sets the reference value for the Relative value measurement (page 62).
MX/MN (MAX/ MIN)		Measures the Maximum or the Minimum value (page 61).
SHIFT → MX/MN (FILTER)		Selects the digital filter type for the signal sampling (page 79).
2nd (Display) / LOCAL		As the 2nd key, selects the measurement item on the 2nd display (page 49). Pressing and holding for more than 1 second turns off the 2nd display. As the Local key, releases the remote control and returns the instrument to local panel operation (page 132).
SHIFT → 2nd (Menu)		Enters the configuration mode for; System Settings, Measurement Settings, ADC Settings, Frequency/Period Settings, I/O Settings, TX TERM Settings and Scanner Settings.

Rear Panel Overview



Power Cord Socket



Accepts the power cord. AC 100/120/220/240V ±10%, 45Hz~66Hz, 360Hz~440Hz.

For power on sequence, see page 21.

Fuse Socket



Holds the main fuse:

100/120 VAC: 0.315AT

220/240 VAC: 0.125AT

For fuse replacement details, see page 213.

RS-232C port



Accepts an RS-232C cable for remote control; DB-9 male connector.

For remote control details, see page 133.

USB device port		Accepts a USB device cable for remote control; Type A, female connector. For remote control details, see page 132.
CAL key port		Reserved for internal purposes such as firmware updates and calibration.
Digital I/O port		Accepts a digital I/O cable for the Hi/Lo limit tests; DB-9 pin, female connector. For digital I/O details, see page 124.
Optional slot x1	Accepts the optional 16 channel scanner module. For scanner details, see page 103. 	
Optional Communication port		Accepts an optional GPIB or Ethernet card.

Set Up

Tilt Stand

Tilt stand steps



Pull out the handle sideways and rotate it.



Place the unit horizontally,



Or in the tilt stand position.



Place the handle vertically for hand carry.

Power Up

Steps

1. Ensure the correct line voltage is lined up with the arrow on the fuse holder. If not, see page 213 to set the line voltage and fuse.



2. Connect the power cord to the AC Voltage input.



Note

Make sure the ground connector on the power cord is connected to a safety ground. This will affect the measurement accuracy.

3. Push to turn on the main power switch on the front panel.



4. The display shows the model name and the version for a few seconds.
Example: GDM-8261A, V1.00

5. Followed by the default measurement settings.

6. And the interface I/O settings.



7. Then the default setting appears.
   Example: DCV, Auto, 100mV range



BASIC MEASUREMENT

ACV DCV ACI DCI 2/4W →|/•)) Hz/P TEMP

Overview	Basic Measurement Overview	25
	Refresh Rate	25
	Reading Indicator	26
	Manual/Automatic Triggering	27
Voltage	AC/DC Voltage Measurement	27
	Select Voltage Range	28
	Voltage Conversion Table	30
	Crest Factor Table	31
Current	AC/DC Current Measurement	32
	Select Current Range	33
Resistance	2W/4W Resistance Measurement	34
	Select Resistance Range	35
Diode	Diode Test	37
Continuity	Continuity Test	38
	Set Continuity Threshold	39
	Select Beeper Setting	40
Frequency/ Period	Frequency/Period Measurement	41
	Select Frequency/Period Voltage Range	42

continued next page

Temperature	Temperature Measurement	43
	Select Thermocouple Type	44
	Set Reference Junction Temperature (T-CUP)	45
	Select Temperature Sensor Type	46
	Set User RTD	47

Basic Measurement Overview

Background

Basic measurement refers to the eight types of measurements assigned to the upper row keys on the front panel.



Measurement type

ACV	AC Voltage
DCV	DC Voltage
ACI	AC Current
DCI	DC Current
2/4W	2-wire and 4-wire Resistance
→+ •))	Diode/Continuity
Hz/P	Frequency/Period
TEMP	Celsius/Fahrenheit Temperature

Advanced measurement

Advanced measurement (page 55) mainly refers to the operation using the result obtained from one or more of the basic measurements.

Refresh Rate

Background

Refresh rate defines how frequently the GDM-8261A captures and updates measurement data. A faster refresh rate yields a lower accuracy and resolution. A slower refresh rate yields a higher accuracy and resolution. Consider these tradeoffs when selecting the refresh rate.

For DC measurements, the frequency of the refresh rate depends on the rate settings (S, M, F) and the ADC speed settings (Accurate, Quick) (page 92).

For AC measurements, the refresh rate (S, M, F) is directly tied to the AC bandwidth settings (page 86).

For further details, please see the specifications.

Refresh Rate (Readings/s)	Function	S	M	F
	Continuity / Diode	100	200	300
	DCV/DCI/100Ω~ 100MΩ (Accurate)	5	60	240
	DCV/DCI/100Ω~ 100MΩ (Quick)	30	600	2400
	ACV/ACI	1.2 (sec/reading)	3.38	30
	Frequency / Period	1	10	100

Selection steps

1. Press the Shift key followed by the AUTO (RATE) key. The refresh rate switches to the next.



2. The refresh rate indicator shows the current status. S→M→F→S

Reading Indicator

Background

The reading indicator * next to the 1st display flashes according to the refresh rate setting.

When no data is captured

When there is no captured data, the reading indicator flashes once every two seconds (slower than the normal refresh rate), indicating the DMM is in standby mode.

Manual/Automatic Triggering

Automatic triggering (default)	The GDM-8261A triggers according to the refresh rate. See the previous page for refresh rate setting details.
Manual triggering	Press the Trig key to trigger measurement manually. The trigger must be set to external (EXT) for manual triggering. See page 76.

AC/DC Voltage Measurement

Voltage type	AC	0 ~ 750V
	DC	0 ~ 1000V
1. Activate ACV/ DCV	Press the ACV (AC Voltage) key or DCV (DC Voltage) key. 	
2. ACV/DCV mode display appears		
	AC or DC + V	Indicates AC, DC voltage
	AUTO	Indicates Automatic range selection
	100mV	2nd display shows the Voltage range
3. Connect the test lead and measure	Connect the test lead between the V and the COM port. The display updates the reading. 	

Select Voltage Range

Auto range

To turn the automatic range selection On/Off, press the AUTO key.

Manual range

Press the Up or the Down key to select the range. The AUTO indicator turns Off automatically. If the appropriate range is unknown, select the highest range.

Selection list

Range	Resolution	Full scale @ slow rate
100mV	0.1μV	119.9999mV
1V	1μV	1.199999V
10V	10μV	11.99999V
100V	100μV	119.9999V
750V (AC)	1mV	750.000V
1000V (DC)	1mV	1000.000V

Note:

For more detailed parameters, see the specifications on page 217.

DC Voltage Range Note:

DC voltages with AC components cannot be accurately measured if the DC+AC component exceed the ADC dynamic range for the selected DC range. Any voltage exceeding the ADC dynamic range will be clipped at the upper/lower range limit. Under these conditions the range that is chosen with the Auto range function may be too small.

Example:



DC 1V Range

A,B: Input exceeds the ADC dynamic range.

C,D: The DCV offset causes the input to exceed the upper ADC dynamic range.

E: The DCV offset causes the input to exceed the lower ADC dynamic range.

The DC voltage range should be manually selected when any of the following conditions are true:

1. When DCV measurement is used.
2. When the signals being measured contain both DC and AC components.
3. When the amplitude of the AC component in the measured signal is higher or lower than the dynamic range of the range being currently selected by auto-range function.

DCV Voltage Range Selection List

DCV Range	ADC Dynamic Range
DC100mV	max±200mV
DC1V	max±2V
DC10V	max±20V
DC100V	max±200V
DC1000V	max±1000V

Voltage Conversion Table

This table shows the relationship between AC and DC reading in various waveforms.

Waveform	Peak to Peak	AC (True RMS)	DC
Sine 	2.828	1.000	0.000
Rectified Sine (full wave) 	1.414	0.435	0.900
Rectified Sine (half wave)	2.000	0.771	0.636
Square 	2.000	1.000	0.000
Rectified Square	1.414	0.707	0.707
Rectangular Pulse 	2.000	2K $K=\sqrt{(D-D^{2})}$ D=X/Y	2D D=X/Y
Triangle Sawtooth 	3.464	1.000	0.000

Crest Factor Table

Background

Crest factor is the ratio of the peak signal amplitude to the RMS value of the signal. It determines the accuracy of AC measurement.

If the crest factor is less than 3.0, voltage measurement will not result in error due to dynamic range limitations at full scale.

If the crest factor is more than 3.0, it usually indicates an abnormal waveform as seen from the below table.

Waveform	Shape	Crest factor
Square wave		1.0
Sine wave		1.414
Triangle sawtooth		1.732
Mixed frequencies		1.414 ~ 2.0
SCR output 100% ~ 10%		1.414 ~ 3.0
White noise		3.0 ~ 4.0
AC Coupled pulse train		>3.0
Spike		>9.0

AC/DC Current Measurement

Background	The GDM-8261A has two input ports for current measurement. A 1A terminal for current less than 1.2A and a 10A port for measurements up to 10A. The GDM-8261A also features a "Current Input Port Auto-Detect" feature (default, off). For details, see page 87.	
Current type	AC	0 ~ 10A
	DC	0 ~ 10A
1. Activate ACI/ DCI	Press the ACI (AC Current) key or the DCI (DC Current) key.	ACI or DCI
2. ACI/DCI mode display appears		
	AC or DC + A	Indicates AC or DC Current (Note: AC = true RMS)
	AUTO	Indicates Automatic range selection
	10A	2nd display shows the Current range
3. Connect the test lead and measure	Connect the test lead between the 10A terminal and COM port or DC/AC 1A terminal and COM port, depending on the current. For current ≤ 1.2A use the 1A terminal; For current up to 10A use the 10A port. The display updates the reading.	

0~1.2A



0~10A



Select Current Range

Auto range

To turn the automatic range selection On/Off, press the AUTO key.

Manual range

Press the Up or the Down key to select the range. AUTO indicator turns Off automatically. If the appropriate range is unknown, select the highest range.

Selection list

Range	Resolution	Full scale @ slow rate
100µA(DC only)	0.1nA	119.9999µA
1mA	1nA	1.199999mA
10mA	10nA	11.99999mA
100mA	0.1µA	119.9999mA
1A	1µA	1.199999A
10A	10µA	10.00000A

DC Current Range Note:

DC currents with AC components cannot be accurately measured if the DC+AC component exceed the ADC dynamic range for the selected DC range. Any current exceeding the ADC dynamic range will be clipped at the upper/lower range limit. Under these conditions the range that is chosen with the Auto range function may be too small.



DC 1mA Range

A,B: Input exceeds the ADC dynamic range.

C,D: The DCI offset causes the input to exceed the upper ADC dynamic range.

E: The DCI offset causes the input to exceed the lower ADC dynamic range.

The DC current range should be manually selected when the following conditions are true:

1. When DCI measurement is used.
2. When the signals being measured contain both DC and AC components.
3. When the amplitude of the AC component in the measured signal is higher or lower than the dynamic range of the range being currently selected by auto-range function.

DCI Current Range Selection List

DCI Range	ADC Dynamic Range
DC 100uA	max±2mA
DC 1mA	max±2mA
DC 10A	max±40mA
DC 100A	max±200mA
DC 1A	max±1.2A
DC 10A	max±10A

2W/4W Resistance Measurement

Measurement type	2-wire	Uses the standard V-COM ports. Recommended for measuring resistances larger than 1kΩ.
	4-wire	Compensates the test lead effect using the 4W compensation ports, in addition to the standard V-COM ports. Recommended for measuring sensitive resistances smaller than 1kΩ.
1. Activate resistance measurement	For 2-wire resistance measurement, press the 2W/4W key once.	2/4W
	For 4-wire resistance measurement, press the 2W/4W key twice.	2/4W 2/4W

2. 2W/4W resistance mode display appears

2W or 4W + Ω	Indicates 2W or 4W Resistance mode
AUTO	Indicates Automatic range selection
1K	2nd display shows the Resistance range

3. Connect the test lead and measure

Connect the test lead. For 2-wire resistance, use the **Ω** (V) and the COM port. For 4-wire resistance, use the **Ω** (V) and the COM port, plus the 4W sense, and LO port for sensing. The display updates the reading.

2W connection



4W connection



Select Resistance Range

Auto range

To turn the automatic range selection On/Off, press the AUTO key.

Manual range

Press the Up or the Down key to select the range. AUTO indicator turns Off automatically. If the range is unknown, select the highest range.

Selection list

Range	Resolution	Full scale @ slow rate
100Ω	0.1μΩ	119.9999Ω
1kΩ	1μΩ	1.199999kΩ
10kΩ	10μΩ	11.99999kΩ
100kΩ	100μΩ	119.9999kΩ
1MΩ	1Ω	1.199999MΩ

	10MΩ	10Ω	11.99999MΩ
	100MΩ	100Ω	119.9999MΩ

Note	For more detailed range, see the specifications at page 217.

Diode Test

Background	Diode test checks the forward bias characteristics of a diode by running a constant forward bias current, approx. 1mA, through the DUT.
1. Activate diode test	Press the →|/•)) key once.
2. Diode mode display appears	
	→| + V — Indicates Diode test
	DIODE — 2nd display shows the title
3. Connect the test lead and measure	Connect the test lead between the →| and COM port; Anode-V, Cathode-COM. The display updates the reading. 

Continuity Test

Background	Continuity test checks that the resistance in the DUT is low enough to be considered continuous (of conductive nature).
1. Activate continuity test	Press the ⊣/•)) key twice. 
2. Continuity mode display appears	
	•)) + Ω Indicates Continuity test
	CONT 2nd display shows the title
3. Connect the test lead and measure	Connect the test lead between the Ω and the COM port. The display updates the reading. 

Set Continuity Threshold

Background	Continuity threshold defines the maximum resistance allowed in the DUT when testing the continuity.
Threshold Range	0 ~ 1000Ω, 1Ω resolution, 10Ω default

1. Activate threshold setting

1. Press the Shift key, the 2nd key, the Right key. The measurement menu appears.



2. Press the Down key, the Right key, the Enter key. The continuity threshold setting appears.



2. Edit threshold

1. Move the cursor (the flashing digit) using the Left/Right key.



2. Change the value using the Up/Down key.

Range: 1 ~ 1000Ω, 1Ω resolution, default 10Ω

3. Go back to the default display

Press the Enter key to confirm the edited threshold. Press the Exit key to go back to the default display.



Select Beeper Setting

Background	Beeper setting defines how the GDM-8261A notifies the continuity test result to the user. When the Beeper setting is off it will also turn the keypad sound off.	
Beeper parameter	Pass	Beeps when the test result is pass
	Fail	Beeps when the test result is fail
	Off	Beep function is turned Off

1. Activate beeper setting menu

1. Press the Shift key followed by the 2nd (Menu) key. The system menu appears.



2. Press the Down key. The beep menu appears.

3. Press the Down key. The beep setting appears.



2. Select the beep setting

To change the setting, press the Up/Down key.

Beeper type: Pass (beep when pass), Fail (beep when fail, default), Off (beep off)

3. Go back to the default display

Press the Enter key to confirm. Press the Exit key to go back to the default display.



Frequency/Period Measurement

1. Activate frequency/period measurement	To measure Frequency, press the Hz/P key once.	Hz/P
	To measure the Period, press the Hz/P key twice.	Hz/P Hz/P

2. Frequency (Period) mode display appears



Hz (S)	Indicates Frequency (period) measurement
AUTO	Indicates Automatic range selection
FREQ (PERIOD)	2nd display shows the measurement mode

3. Connect the test lead and measure

Connect the test lead between the V and the COM port. The display updates the reading.



Select Frequency/Period Voltage Range

Frequency/Period mode	To select between period/frequency voltage range, press the 2nd key twice.	2ND 2ND
Auto range	To turn the automatic range selection On/Off, press the AUTO key.	AUTO
Manual range	Press the Up or the Down key to select the range. AUTO indicator turns Off automatically. If the appropriate range is unknown, select the highest range.	▲ ▼

Range		
	Frequency	3Hz~300kHz
	Period	3.3μs ~333.3ms
	Voltage Range	100mV~750V

Temperature Measurement

Background	The GDM-8261A can measure temperature using either thermocouples or RTD sensors. For thermocouples, the GDM-8261A accepts a thermocouple input and calculates the temperature from the voltage fluctuation. The thermocouple type and reference junction temperature are also considered. For RTD sensors, the GDM-8261A calculates voltage based on the resistance of the chosen RTD.
1. Activate temperature measurement	For Celsius units, press the TEMP key once. For Fahrenheit units, press the TEMP key twice.
2. Temperature mode display appears	 °C — Indicates Temperature measurement TYPE J — 2nd display shows the thermocouple/RTD type
3. Connect the test lead and measure	Connect the sensor lead between the V and the COM port for thermocouple and 2W RTD measurements. For 4W RTD measurements, also connect the sense HI and LO ports to the sensor. The display updates the reading.
	Thermocouple 2W RTD 4W RTD 
Range	RTD: -200°C ~ +600°C (sensor dependent) Thermocouple: -210°C ~ +1820°C (sensor dependent)

Select Thermocouple Type

Background

The GDM-8261A accepts thermocouple inputs and calculates the temperature from the voltage difference of two dissimilar metals. Thermocouple type and reference junction temperature are also considered.

Parameter

Thermocouple	Range	Resolution
E	-200 to +1000°C	0.002 °C
J	-210 to +1200°C	0.002 °C
T	-200 to +400°C	0.002 °C
K	-200 to +1372°C	0.002 °C
N	-200 to +1300°C	0.003 °C
R	-50 to +1768°C	0.01 °C
S	-50 to +1768°C	0.01 °C
B	+350 to +1820°C	0.01 °C

1. Open sensor selection menu

Press the Shift key, then the TEMP (Sensor) key. The sensor selection menu appears on the display.



2. Select sensor type

Press the Left and Right arrow keys and select T-CUP (thermocouple).

3. Select sensor

Press the Down key twice. The sensor selection menu appears on the display.

4. Select sensor type

Press the Up/Down key. The thermocouple type switches to the next one.

5. Confirm and go back to the default display	Press the Enter key to confirm. Press the Exit key to go back to the default display.	AUTO (ENTER) → SHIFT / EXIT

Set Reference Junction Temperature (T-CUP)

Background

When a thermocouple is connected to the GDM-8261A, the temperature difference between the thermocouple lead and the GDM-8261A input terminal should be taken into account and be cancelled; otherwise an erroneous temperature might be added.

Type	Range	Resolution
SIM (simulated)	0 ~ +50°C	0.01°C

The terminal temperature is manually defined by the user. Default value: 23.00

1. Open reference junction menu

Press the Shift key, then the TEMP (Sensor) key. The sensor selection menu appears on the display.

SHIFT / EXIT → SENSOR (TEMP)

Press the Left and Right arrow keys and select T-CUP (thermocouple).

HOLD TRIG

Press Down, Right arrow key and then Down again. The reference junction selection menu appears on the display.

▼ TRIG ▼

2. Edit reference temperature	Use the Left/Right key to move the cursor, and use the Up/Down key to change the value. Default: 23.00	
	Press the Enter key to confirm the value, or the Exit key to cancel. The display goes back to the previous menu.	

Select Temperature Sensor Type

Background	The GDM-8261A supports a number of thermocouple types as well as 2 or 4 wire RTD. It is important to specify the type of temperature sensor used.		
Parameter	RTD type	Range	Resolution
	All (based on PT100)	-200~600°C	0.001°C
1. Open sensor selection menu	Press the Shift key, then the TEMP (Sensor) key. The sensor selection menu appears on the display.		
2. Select sensor type	Press the Left and Right arrow keys to highlight the 2WRTD or 4WRTD sensor type. Press the down key to go to the next menu level.		

3. Select sensor

Press the Up and Down keys to highlight the RTD sensor type.

RTD Type: PT 100, PT 3916, PT 385, F 100, D 100, USER

4. Confirm and go back to the default display

Press the Enter key to confirm. Press the Exit key to go back to the default display.



Set User RTD

Background

The USER setting allows any custom RTD sensor coefficients to be used. The USER setting can configure the alpha, beta and delta coefficients, as defined by the Callendar–Van Dusen equation.

Coefficient range	
Alpha	0.000000~10.00000
Beta	0.000000~10.00000
Delta	0.000000~10.00000

1. Open sensor selection menu

Press the Shift key, then the TEMP (Sensor) key. The sensor selection menu appears on the display.



2. Select sensor type

Press the Left and Right arrow keys and select 2WRTD or 4WRTD



	Press the Down key twice. The RTD selection menu appears on the display.	▼ ▼
	Use the Up/Down keys to select USER.	▲ ▼

3. Open USER type menu	Press Enter. The alpha coefficient menu appears on the display.	AUTO ENTER

4. Edit coefficient values	Use the Left/Right key to move the cursor, and use the Up/Down key to change the coefficient value. Default: 0.00385	◀HOLD TRIG▶ ▲ ▼
	Press the Enter key to confirm the value and move onto to the next coefficient. Default: Alpha 0.00385, Beta 00.10863, Delta 1.49990	AUTO ENTER (confirm)
	Press the Exit key to cancel at any time. The display goes back to the previous menu.	SHIFT / EXIT (cancel)

DUAL MEASUREMENT

Dual Measurement

Background

The dual measurement mode allows you to use the 2nd display to show another item, thus viewing two different measurement results at once.

When the multimeter is used in dual measurement mode, both displays are updated from either a single measurement or from two separate measurements.

If the primary and secondary measurement modes have the same range, rate and rely on the same fundamental measurement, then a single measurement is taken for both displays; such as ACV and frequency/period measurements.

If the primary and secondary displays use different measurement functions, ranges or rates, then separate measurements will be taken for each display. For example, ACV and 2W/4W resistance measurements.

Example Dual Measurement Applications

Combination		Applications
DCV	ACV	• Measure DC signals that have AC components*. For example: Measure the DC offset and AC noise from an amplifier output. Measure the DC output voltage and ripple from a DC power supply. * Ripple or the AC noise frequency must be within the DMM's measurable AC bandwidth for the noise to be measured.

Amplifier Output



DC Power Supply Output



DCV DCI

- Monitor the voltage and current present on a component in a circuit or the output voltage and current of a DC power supply.

Monitor Voltage and Current



ACV Hz

- Measure the frequency response of devices such as amplifiers or buffers*.

  * The frequencies of the amplifier output must be within the DMM's measurable AC bandwidth for the amplitude at a spot frequency to be measured accurately.

Frequency Response



The following table shows the available measurement combinations.

1st Display[2]	2nd Display[2]					
	ACV	DCV	ACI	DCI	Hz/P	2W/4W[1]
ACV	●	●	●	●	●	—
DCV	●	●	●	●	●	—
ACI	●	●	●	●	●	—
DCI	●	●	●	●	●	—
Hz/P	●	●	●	●	●	—
2W/4W[1]	—	—	—	—	—	●

Note

[1] 2W/4W measurements in combination with other measurements are possible but may not be practical as the measurement accuracy is not guaranteed.

[2] When two different measurements are taken, there is a switching delay between the first measurement and the second measurement.

1st Measurement item setting

Choose a basic measurement from the above table. Example: press the ACI key.

Page 23

Example: ACI

2nd Measurement item setting	Press the 2nd key, then the target item (example: ACV). The display updates the measurement result. (example: ACI + ACV)	2ND → ACV



1st Display	Shows the primary measurement result
2nd Display	Shows the secondary measurement result
2^{ND}	Indicates that dual measurement is active

Editing 1st or 2nd measurement item settings	After the secondary measurement function has been activated, the rate, range and measurement item can be edited for either the primary or secondary display. Note however, it is more practical to configure the first or second measurement items before activating dual measurement mode.	
1. Select active display	Toggle whether the primary or secondary display is the active display by pressing the 2ND key: Primary display: 2ND *is not visible* on the display Secondary display: 2ND *is* visible on the display *Do not hold the 2ND key. This will turn the dual measurement off.*	2ND (toggle active display)
2. Edit active display settings	Edit the range, rate or measurement item for the active display in the same way as for single measurement operation. See the Basic Measurement chapter for details.	Page 23
Turn Off 2nd Measurement	To turn Off the 2nd measurement, press and hold the 2nd key for more than 1 second.	2ND (hold 1 sec.)

Connect the test leads and measure

When using the dual measurement function, the connection method and number of test leads required depends on the measurement combination. Use the connect diagrams below as guide when taking dual measurements.

Voltage and Frequency/Period Measurement



2W/4W Resistance Measurement



Voltage/Frequency/Period and Current Measurement



Note: DC Current measurements will be displayed as a negative value as the polarity of the current leads has been reversed.

Please take into account the resistance of the test leads and internal resistance of the current connection as it is in series with the test circuit.

The above measuring configuration is used to measure the voltage present on the resistance under test and the current through the resistance under test when using the DCI/DCV or ACI/ACV dual measurement function.

ADVANCED MEASUREMENT



Overview	Advanced Measurement Overview	56
	Refresh Rate	56
	Reading Indicator	57
	Common Attribute: Manual/Automatic Triggering	57
dBm/dB	dBm/dB/W Measurement	58
	Measure dBm/W	58
	Measure dB	59
Max/Min	Max/Min Measurement	61
Relative	Relative Value Measurement	62
Hold	Hold Measurement	64
Compare	Compare Measurement	65
Math	Measure MX+B	68
	Measure 1/X	70
	Measure Percentage	70
	Statistics Calculations	71

Advanced Measurement Overview

Background

Advanced measurement mainly refers to the type of measurement which uses the result obtained by one of the basic measurements: ACV, DCV, ACI, DCI, 2/4W, Diode/Continuity, Frequency/Period, and Temperature.



Advanced Measurement	Basic Measurement					
	AC/DCV	AC/DCI	2/4W	Hz/P	TEMP	⊣/•))
dB	●	—	—	—	—	—
dBm	●	—	—	—	—	—
Max/Min	●	●	●	●	●	—
Relative	●	●	●	●	●	—
Hold	●	●	●	●	●	—
Compare	●	●	●	●	●	—
Math	●	●	●	●	●	—

Refresh Rate

Background

Refresh rate defines how frequently the GDM-8261A captures and updates measurement data. A faster refresh rate yields a lower accuracy and resolution. A slower refresh rate yields a higher accuracy and resolution. Consider these tradeoffs when selecting the refresh rate.

For DC measurements, the frequency of the refresh rate depends on the rate settings (S, M, F) and the ADC speed settings (Accurate, Quick) (page 92).

For AC measurements, the refresh rate (S, M, F) is directly tied to the AC bandwidth settings (page 86).

For further details, please see the specifications.

Refresh Rate (Readings/s)	Function	S	M	F
	Continuity / Diode	100	200	300
	DCV/DCI/100Ω~100MΩ (Accurate)	5	60	240
	DCV/DCI/100Ω~100MΩ (Quick)	30	600	2400
	ACV/ACI	1.2 (sec/reading)	3.38	30
	Frequency/Period	1	10	100

Selection steps

1. Press the Shift key followed by the AUTO (RATE) key. The refresh rate switches to the next.



2. The refresh rate indicator shows the current status. S→M→F→S

Reading Indicator

Background

The reading indicator * next to the 1st display flashes according to the refresh rate when the captured data is updated on the display.

When no data is captured

When there is no captured data, the reading indicator flashes once every two seconds (slower than the normal refresh rate), indicating the DMM is in the waiting mode.

Common Attribute: Manual/Automatic Triggering

Automatic triggering (default)

The GDM-8261A triggers according to the refresh rate. See the previous page for refresh rate setting details.

Manual triggering	Press the Trig key to trigger the measurement manually. The trigger must be set to external (EXT) for manual triggering. See page 76.	

dBm/dB/W Measurement

Applicable to		
Background	Using the ACV or DCV measurement result, the GDM-8261A calculates the dB, dBm or W value based on a reference resistance value in the following way.	
	dBm	10 x $\log_{10}$ (1000 x $Vreading^2$ / Rref)
	dB	dBm – dBmref
	W	$Vreading^2$/Ref
Parameters	Vreading	Input Voltage, ACV or DCV
	Rref	Reference resistance simulating an output load
	dBmref	Reference dBm value

Measure dBm/W

Activate dBm	Press the Shift key followed by the ⊣/•)) key. The 1st display shows dBm, and the 2nd display shows the reference resistance.	
dBm result appears		
	dBm	Indicates dBm measurement
	600Ω	2nd display indicates the reference resistance

Select reference resistance	To change the reference resistance, press the Up/Down key. The new resistance appears in the 2nd display. The following is the resistance list.

2	4	8	16	50	75	93
110	124	125	135	150	250	300
500	600	800	900	1000	1200	8000

View result in Watts	When the reference resistance is less than 50Ω, it is possible to calculate the watt value. If the reference resistance is greater than 50Ω then this step can be ignored. To calculate the power, press the Shift key followed by the ⊣/•)) key again. 
Watt result appears	

W	Indicates W measurement
16Ω	2nd display indicates the reference resistance

Deactivate dBm/W measurement	To cancel the dBm/W measurement, press the Shift key followed by the ⊣/•)) key, or simply activate another measurement. 

Measure dB

Background	dB is defined as [dBm−dBmref]. When the dB measurement is activated, the GDM-8261A calculates the dBm using the reading at the first moment and stores it as dBmref.
Activate dB	Press the Shift key followed by the Hz/P key. The 1st display shows dB, and the 2nd display shows the current Voltage reading. 

dB result appears		
	dB	Indicates dB measurement
	-00.617mV	Indicates the present Voltage reading
dBmref	Press the 2nd key to see the dBm ref value.	
Deactivate dB measurement	To cancel the dB measurement, press the Shift key followed by the Hz/P key, or simply activate another measurement.	

Max/Min Measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP	
Background	Maximum and Minimum measurement stores the highest (maximum) or lowest (minimum) reading and shows it on the 1st display when the 2nd key is pressed.	
1. Activate Max/Min	For Max measurement, press the MX/MN key once.	MX/MN
	For Min measurement, press the MX/MN key twice.	MX/MN MX/MN
2. Max (Min) result is activated		
	MIN (MAX)	Indicates Min (Max) measurement is activated
	1V	2nd display shows the Min (Max) range
View Max (Min)value	Press the 2nd key to view the Max (Min) value.	2ND
Max (Min) measurement appears		
	2nd display	Indicates that the Max (Min) value is displayed on the 1st display
	1st display	Shows the Max (Min)value at full scale
Deactivate Max/Min measurement	To cancel the Max/Min measurement, press the MX/MN key for 2 seconds, or simply activate another measurement.	MX/MN (hold for 2 seconds)

Relative Value Measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP
Background	Relative measurement stores a value, typically the data at the moment, as the reference. The following measurement is shown as the delta between the reference. The reference value will be cleared upon exit.
1. Activate Relative measurement	Press the REL key. The measurement reading at the moment becomes the reference value. REL
2. Relative measurement display appears	

REL	Indicates Relative value measurement
2nd display	Shows the measurement range.
1st display	Shows the delta between the current measurement data and the reference value

View reference (REL) value	Press the 2nd key to view the reference (REL) value. 2ND
Reference (REL) measurement display appears	

2nd display	Indicates that the reference (REL) value is displayed on the 1st display
1st display	Shows the reference (REL)value at full scale

Manually set the reference value	1. To set the reference (REL) value manually, press the Shift key followed by the REL key. The setting appears.	SHIFT / EXIT → REL# (REL)

REL	Indicates Relative measurement
1st display	Shows the reference value (to full scale)
2nd display	Indicates Relative value modification

2. Use the Left/Right key to move the flashing point (cursor), and use the Up/Down key to change the value.



3. Press the Enter key to confirm the value, or the Exit key to cancel. The display switches to measurement.



(confirm)

(cancel)

Deactivate Relative measurement

To cancel the Relative measurement, press the REL key again, or simply activate another measurement.

Hold Measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP
Background	The Hold Measurement function retains the current measurement data and updates it only when it exceeds the set threshold (as a percentage of the retained value).
1. Activate Hold measurement	Press the Hold key.
2. Hold measurement display appears	
	HOLD: Indicates Hold measurement
	2nd display: Shows the Hold threshold
	1st display: Shows the measurement data.
3. Select hold threshold	Select the hold threshold using the Up/Down key. The 2nd display changes accordingly.
	Range: 0.01%, 0.1%, 1%, 10%
Deactivate Hold measurement	To cancel the Hold measurement, press the Hold key for 2 seconds, or simply activate another measurement.

Compare Measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP
Background	Compare measurement checks and updates if the measurement data stays between the upper (high) and lower (low) limit specified.
1. Activate Compare measurement	Press the Shift key, then the Hold (Comp) key. 
2. High limit setting	

1st display	Shows the high limit value
2nd display	Indicates high limit setting

1. Use the Left/Right key to move the cursor (flashing point) between high/low setting, digits, and decimal point.





2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm editing and move to the low limit setting.

3. Low limit setting

1st display	Shows the low limit value
2nd display	Indicates low limit setting

1. Use the Left/Right key to move the cursor (flashing point) between high/low setting, digits, and decimal point.



2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm editing. The compare measurement starts right away.

4. Compare measurement appears

COMP	Indicates Compare mode
2nd display	Shows the compare measurement result: Pass, High, or Low.

5. Result	High	If the 2nd display shows High, the result is above the High limit.
		Digital I/O: FAIL Out (Pin 6) and HIGH Limit FAIL Out (Pin 7) are activated.
	Low	If the 2nd display shows Low, the result is below the Low limit.
		Digital I/O: FAIL Out (Pin 6) and LOW Limit FAIL Out (Pin 8) are activated.
	Pass	If the 2nd display shows Pass, the result is staying between the High and the Low limit.
		Digital I/O: PASS Out (Pin 5) is activated.
Digital I/O	The Compare measurement result comes out from the rear panel Digital I/O terminal. For the terminal details, see page 124.	
Deactivate Compare measurement	To cancel the Compare measurement, press the Shift key followed by the Hold (Comp) key, or simply activate another measurement.	

Math Measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP	
Background	Math measurement runs four types of mathematical operations, MX+B, 1/X, Percentage and Stats, based on the other measurement results.	
Math type	MX+B	Multiplies the reading (X) by the factor (M) and adds/subtracts offset (B).
	1/X	Inverse. Divides 1 by the reading (X).
	Percentage	Runs the following equation. $\frac{(\text{ReadingX} - \text{Reference})}{\text{Reference}} \times 100\%$
	Stats	Performs standard deviation calculations on measurement data.

Measure MX+B

1. Activate MX+B

Press the Shift key followed by the 2/4W (Math) key. The MX+B setting appears.



2. Set the factor (M)

1st display	Shows the factor (M)
2nd display	Indicates MX+B (The letter M flashes)

1. Use the Left/Right key to move the cursor (flashing point) between the factor, digits, and decimal point.





2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm editing and move to offset setting.

3. Set the offset (B)

1st display	Shows the offset (B)
2nd display	Indicates MX+B (The letter B flashes)

1. Use the Left/Right key to move the cursor (flashing point) between the offset, digits and decimal point. 

2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm the editing. The MX+B measurement result appears.

4. View MX+B

1st display	Shows the calculated result
2nd display	Indicates MX+B
MATH	Indicates Math operation

Measure 1/X

1. Activate 1/X

Press the Shift key, the 2/4W (Math) key, the Down key twice. The 1/X setting appears.



2. View 1/X

Press the Enter key to view the 1/X measurement result.

1st display	Shows the 1/X value
2nd display	Indicates 1/X
MATH	Indicates Math operation

Measure Percentage

1. Activate Percentage

Press the Shift key, the 2/4W (Math) key, the Up key twice. The Reference setting appears. The Percentage is calculated as: [Reading−Reference]/Reference x 100%.



2. Set the reference number

1st display	Shows the reference number
2nd display	Indicates Percentage setting

1. Use the Left/Right key to move the cursor (flashing point) between the digits and decimal point.



2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm editing.

ENTER

3. View Percentage

1st display	Shows the calculated result
2nd display	Indicates the Percentage measurement
MATH	Indicates Math operation

Statistics Calculations

Background

The Analyze Stats menu allows you to make statistical calculations on a continuous or user-defined number of measurement counts. The measurements supported include, Maximum, Minimum, Average and Standard deviation.

Number of counts	User Defined	2~100,000 counts
	Continuous	9,999,999 count

1. Activate Statistics

Press the Shift key, the 2/4W (Math) key, the Up key. The Analyze Stats setting menu appears.

SHIFT/ EXIT → MATH 2/4W →

2. Set Count

Press the Enter key to set the number of measurements (counts) that will be used for the Stats function. The Count menu appears.

AUTO
ENTER

1st display	Shows the count number as continuous
2nd display	Indicates the count setting

2a.Continuous count

1. To set the count to Continuous and to start measurement, press Enter when CONTINU is displayed on the 1st display.

AUTO
ENTER

2. Measurement starts automatically.

2b. User-defined count

1. To set a user-defined count number, press the Left key followed by Up when CONTINU is displayed on the screen. The Count setting menu will appear.

→ HOLD
→ ▲

1st display	Shows the count number (2~100,000)
2nd display	Indicates the count setting

2. Use the Left/Right key to move the flashing point (cursor), and use the Up/Down key to change the count number.

HOLD TRIG
▲ ▼

	3. Press the Enter key to confirm editing and to start measurement.	AUTO ENTER
3. View Data		
	1st display — Shows the current count number/measurement	
	2nd display — Indicates the count measurement mode.	
	MATH — Indicates Math operation	
	Press the 2nd key to cycle through the different statistical data measurements.	2ND
	COUNT — Indicates the current measurement count	
	MIN — Indicates the minimum data value	
	MAX — Indicates the maximum data value	
	AVG — Indicates the mean (average) value	
	STDEV — Indicates the standard deviation of the data	
Stop/Restart Measuring	Press the SHIFT key for 2 seconds to stop or restart measuring.	SHIFT / EXIT (hold for 2 seconds)
		
	S: — Indicates the measurement has started	
	P: — Indicates the measurement has stopped	
Exit	Press the SHIFT key and the 2/4W key to exit.	SHIFT / EXIT → MATH 2/4W

SYSTEM/DISPLAY CONFIGURATION

Refresh Rate	Refresh Rate Setting	75
	View Serial Number	75
Trigger	Manual/Automatic Triggering	76
	Use External Trigger	76
	Set Trigger Delay	78
Filter Settings	Digital Filter Overview	79
	Digital Filter Setting	80
	Analog Filter Settings	82
Display	Display Light Setting	83
Measurement Configuration Settings	D-Shift Settings	84
	Input Resistance Setting	85
	AC Bandwidth Setting	86
	Current Input Port Auto-Detect Setting	87
ADC Settings	Auto-Zeroing	88
	Auto-Gain	90
	ADC Speed Setting	92
Frequency/ Period settings	Input Port Selection	93
	Gate Time Setting	95
Identification Settings	Changing the Identification String	96

Refresh Rate Setting

Background

Refresh rate defines how frequently the GDM-8261A captures and updates the measurement data. A faster refresh rate yields a lower accuracy and resolution. Slower refresh rates yield a higher accuracy and resolution. Consider this trade-off when selecting the refresh rate.

The refresh rate settings are individually set for all measurement modes except for ACV/ACI measurements. ACV/ACI use the same refresh rate settings.

Display/Range

S	6 ½ digits
M	5 ½ digits
F	4 ½ digits

Refresh rate selection

Press the Shift key followed by the AUTO (Rate) key. The refresh rate indicator switches to the next rate setting.



Refresh Rate S→M→F→S

View Serial Number

Background

View the serial number using the System menu.

Panel operation

1. Press the Shift key, the 2nd (Menu) key, followed by the down key. Then press the left key repeatedly until the S/N menu appears.



2. Press the Down key. The serial number is shown on the display.

1st display	Shows 2 characters (AA~ZZ).
2nd display	Shows 6 numbers (000000~99999).

3. Press the Enter key or the Exit key to go back to the previous display.

AUTO ENTER or SHIFT / EXIT

Trigger Setting

Manual/Automatic Triggering

Automatic triggering (default)	The GDM-8261A triggers according to the refresh rate. See the previous page for refresh rate setting details.
Manual triggering	Press the Trig key to trigger measurement manually. See below for details. TRIG

Use External Trigger

Background	The GDM-8261A uses the internal trigger by default, for example to count the frequency and the period. Using an external trigger allows customized triggering conditions.
Signal connection	Connect the external trigger signal to the Digital I/O port located on the rear panel.



DB-9, female



Digital I/O pin assignment



1. Activate external trigger

Press the Shift key followed by the Trig (Int/Ext) key. The EXT indicator appears on the display.



2. Start trigger

Press the Trig key to start triggering manually. The * indicator turns On.



Reading indicator

The reading indicator * does not flash before triggering (can be on or off). After triggering, the indicator flashes according to the external signal trigger timing.

Exit external trigger

Press the Shift key followed by the Trig key. The EXT indicator disappears and the trigger goes back to internal mode.



Set Trigger Delay

Background

Trigger delay defines the time delay between triggering and measurement start. The default is set at 10ms.

Panel operation

1. Press the Shift key, the 2nd (Menu) key, the Right key, the Down key. The delay menu appears.



2. Press the Down key. The delay setting appears.

3. Move the flashing point (cursor) using the Left/Right key. Change the value using the Up/Down key.



4. Press the Enter key to confirm editing and press the Exit key. The display goes back to previous mode.



Range 0 ~ 9999ms, 1ms resolution

Filter Setting

Digital Filter Overview

Filter basics

The GDM-8261A's internal digital filter converts the analog input signal into digital format before passing it to internal circuits for processing. The filter affects the amount of noise included in the measurement result.

Filter type

The digital filter averages a specific number of input signal samples to generate one reading. The filter type defines the averaging method. The following diagrams highlight the differences between the Moving and Repeating filter using 4 samples per reading.

Moving (default)

The Moving filter takes in one new sample and discards the oldest sample per reading. This is the default behavior when the digital filter is not specified, and is recommended for most applications except for the optional scanner operation (page 103).



Repeating

The Repeating filter renews a whole group of samples per reading. This method is recommended when using the optional scanner (page 103).



Filter count	Filter count defines the number of samples to be averaged per reading. More samples offer low noise but a long delay. Less samples offer high noise but a short delay. Range 2 ~ 100
Filter window	Filter window defines the threshold for when the digital filter data is updated again. When the AD data falls in the range between TH and TL, the filter keeps processing. When the AD data falls out of the range between TH and TL, the filter will restart. When measuring unstable signals, appropriately setting the filter window can improve the measurement speed.  TH: Threshold High, TL: Threshold Low
Filter window Formula	Previous data*(1-window)< threshold< previous data*(1+window).There are 5 windows range settings that can be chosen: 10%, 1%, 0.1%, 0.01% and none

Digital Filter Setting

Turn on Filter

1. Press the Shift key followed by the MX/MN (Filter) key.



1st display	Shows the filter count
2nd display	Shows the filter type (flashing)

2. Select the filter type using the Up/Down key.

3. Move the cursor to filter count using the Left/Right key. Change the value using the Up/Down key.



Set Filter Window threshold

4. Press the Enter key to confirm editing.

5. Select the Window threshold using the Up/Down key. The display changes accordingly.

Range	None, 0.01%, 0.1%, 1%, 10%

6. Press the Enter key to confirm editing. The Filter indicator appears on the display.

FILT	Indicates manual Filter setting

Turn off Filter

Press the Shift key followed by the MX/MN (Filter) key. The Filter indicator will disappear from the display.



Analog Filter Settings

Background

The analog filter is a single order low pass filter that can be turned on to attenuate the AC components from a DC signal. This will effectively eliminate the AC component from influencing the automatic range settings.

For example, the analog filter can be turned on to attenuate the AC components of a DC signal that has a superimposed AC voltage with a magnitude that is higher than the measurable range of the DC signal.

The Analog filter setting is off by default. The cutoff frequency for the analog filter is at 500Hz (-3dB).

Note

The analog filter can only be used with DCV and DCI measurements.

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. The Level 1 menu appears.



2. Press the right key twice until Set ADC appears.

3. Press down once to enter the Set ADC menu on level 2.

4. Press the left key until the A-Filter setting is shown.

5. Press the Down key to turn the A-Filter on or off.

1st display Shows the A-FILT setting

6. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Display Setting

Display Light Setting

Background

The display light setting adjusts the brightness of the display reading. Use light 3 or more (brighter) when working indoor; use light 2 or 1 (darker) when working outdoor under the sun.

Level	5 (brightest) ~ 1 (darkest), default = 3

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. The system menu appears.



2. Press the Down key, then the Right key twice. The light menu appears.



3. Press the Down key. The light level setting appears.

1st display	Shows the current display light level

4. Select the level using the Up/Down key.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Measurement Configuration Settings

D-Shift Settings

Background

The D-Shift setting automatically shifts the decimal point depending on the measurement. If D-Shift is turned off, the measured readings will be displayed at the full 6 ½ digits with a fixed decimal place. The D-Shift setting is on by default.

D-Shift On, Off (default, On)

Panel operation

1. Press the Shift key, the 2nd (Menu) key followed by the Right key. The MEAS menu appears.



2. Press the down key, followed by the right key twice to enter the D-SHIFT menu.



3. Press the Down key. The D-Shift setting appears.

1st display Shows the D-Shift setting

4. Select the setting using the Up/Down keys.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Input Resistance Setting

Background

The 0.1V and 1V DC voltage ranges can be set to an input resistance of 10MΩ or 10GΩ. This setting is only applicable for DC Voltage only.

Input Resistance 10MΩ, 10GΩ (default = 10M)

Panel operation

1. Press the Shift key, the 2nd (Menu) key followed by the Right key. The MEAS menu appears.



2. Press the down key followed by the right key three times. The Input Resistance menu appears.





3. Press the Down key. The input resistance setting appears.

1st display Shows the input resistance setting

4. Select the setting using the Up/Down keys.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



AC Bandwidth Setting

Background

Sets the AC Bandwidth (filter) setting for AC measurements. The Slow, Medium, Fast (S, M, F) rate settings are directly tied to the AC bandwidth settings.

Rate	Digits	Input Frequency	Readings/s
S	6 ½	3 Hz – 300 kHz	1.2 (sec/reading)
M	5 ½	20 Hz – 300 kHz (default)	3.38
F	4 ½	200 Hz – 300 kHz	30

Panel operation

1. Press the Shift key, the 2nd (Menu) key followed by the Right key. The MEAS menu appears.



2. Press the down key followed by the left key twice. The AC Bandwidth menu appears.



3. Press the Down key. The input bandwidth setting appears.

1st display Shows the bandwidth setting

4. Select the setting using the Up/Down keys.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Current Input Port Auto-Detect Setting

Background

The Current Input Port Auto-Detect setting will allow the DMM to detect whether current is applied to the 1A or 10A input ports and enables it to set the correct range when Auto range is on.

The Current detect feature works by activating the input port only when a certain Detect Threshold is reached and deactivating the input port when the input current dips below a certain Reset Threshold.



I-DET On, Off (default = On)

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. The system menu appears.



2. Press the Right key, then the down key. Press the left key. The Current detect menu appears.



3. Press the Down key. The input current detect setting appears.



1st display Shows the current detect setting

4. Select the setting using the Up/Down keys.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



ADC Setting

Auto-Zeroing

Background

The Auto Zeroing (A-Zero) function can be used in resistance, TC, RTD, DCV and DCI measurements.

Auto zeroing is used to prevent measurements from drifting by taking offset measurements.

Setting Off, On (default=On)

Theory

The combined offset from the input buffer, A/D driver and ADC is called the total offset. Due to temperature variations inside the GDM-8261A, the offsets for the

Buffer, A/D driver and ADC vary over time, and thus the total offset will also vary over time.

Auto Zero deducts this total offset from the measured signal to obtain a more accurate reading. If Auto Zero is turned off, this total offset will not be deducted from the measured signal.

Auto zero works in the following manner:

Internally, the DMM will periodically short the Buffer's Hi and Lo input to obtain a total offset. The frequency at which the offset is obtained depends on the sample rate.

The diagram below shows how the total offset is obtained.



Applicable Measurement Mode, Rate and Speed settings

Mode	Rate	Accuracy Speed	Quick Speed
DCV, DCI, 4W/2W	S	✓	✓
	M	✓	
	F	✓	

Mode	Rate	
TC, RTD, Diode, Cont	S M	These four measurement modes don't support either accuracy or quick speed.

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. Press the right key twice. The ADC setting menu appears.



2. Press the Down key twice. The A-Zero setting appears.

1st display Shows A-Zero setting

3. Select the setting using the Up/Down key.

4. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Auto-Gain

Background

The Auto-Gain (A-GAIN) setting performs auto gain correction of the internal amplifiers.

Setting Off, On (default=On)

Applicable Measurement Mode, Rate and Speed settings

Mode	Rate	Accuracy Speed	Quick Speed
DCV, DCI, 4W/2W, Resistance	S	✓	✓
	M	✓	
	F	✓	

Mode	Rate	
TC, RTD, Diode, Cont	S M	These four measurement modes don't support either accuracy or quick speed.

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. Press the right key twice to choose the SET ADC menu.



2. Press the Down key and then the Left key twice to choose A-GAIN. Press the Down key. The A-GAIN setting appears.



1st display Shows A-Zero setting

3. Select the setting using the Up/Down key.

4. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



5. A-Zero and A-Gain have an identical time interval of 5 seconds. As can be seen in the diagram below, Auto-Gain correction is performed once after A-Zero has been performed twice.

Expmple
Mode: DCV
Rate: Slow
Accuracy Speed: 650ms



Mode	Rate	Accuracy Speed	Quick Speed
DCV, DCI, 4W/2W	S	650ms	495ms
	M	217ms	
	F	70ms	

Mode	Rate	Below four measurement modes don't support either accuracy or quick speed.
TC, RTD,	S	800ms
	M	184ms
Diode, Cont	S	140ms
	M	80ms

ADC Speed Setting

Background

The analog to digital converters have a Quick and Accurate Speed setting. The ADC Speed settings only apply to DCV, DCI or 2/4W resistance measurements. The ADC Speed settings can only be set if DCV, DCI or 2/4W mode is active.

Setting	Quick, Accurate (default=Accurate)

Speed/Rate Settings

The Speed settings depend on the operating mode and the rate settings.

			Readings/s	
Function	Rate	Digits	Accurate	Quick
DCV, DCI, 2/4W (100Ω ~100MΩ)	S	6 ½	5	30
	M	5 ½	60	600
	F	4 ½	240	2400

All speeds need A-Zero=off, A-Gain=off, fixed range and Trigger Delay=0.

Panel operation

1. Ensure a DC related measurement function is selected.

DCV page 27
DCI page 32
2/4W page 33

2. Press the Shift key followed by the 2nd (Menu) key. Press the right key twice. The SET ADC menu appears.





3. Press the Down key, the right key and then the down key. The Speed settings menu appears.



1st display	Shows the Speed setting

4. Use the Up/Down keys to select either ACCUR or QUICK.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Frequency / Period Settings

Input Port Selection

Background The INJACK settings set which input port is used for frequency or period measurements.

Setting VOLT, 1A, 10A

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. Press the right key three times. The Frequency/Period menu appears.



2. Press the Down key twice. The INJACK setting appears.

1st display Indicates which input port is assigned as the input port.

3. Select the input using the Up/Down key.

4. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Gate Time Setting

Background

The gate time settings determine the accuracy of the frequency and period measurements. The gate time settings are the equivalent to the Fast, Medium and Slow rate settings.

Setting	10ms, 100ms, 1000ms

Rate Settings

The gate time settings are analogous to the rate settings.

Function	Digits	Rate	Readings/s	Gate time
Frequency, Period	6 ½	Slow	1	1000ms
	5 ½	Med.	10	100ms
	4 ½	Fast	100	10ms

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. Press the right key three times. The Hz/P menu appears.



2. Press the Down key, the right key and then the down key. The gate time settings menu appears.





1st display	Shows the gate time setting

3. Select the gate time using the Up/Down key.

4. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Identification Settings

Changing the Identification String

Background

The *IDN? query returns the manufacturer, model number, serial number and system firmware version number. When LANG is set to COMP, a user defined manufacturer and model number is returned with the *IDN? query. Please see the SYSTem:IDNStr command on page 202 for details.

Setting NORM, COMP

Panel operation

1. Press the Shift key followed by the 2nd (Menu) key. The System menu appears.



2. Press the Down followed by the Left key. The LANG menu appears. Press the Down key to enter the LANG menu.



1st display Indicates the LANG setting.

3. Select NORM or COMP using the Up/Down key.

4. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



STORE/RECALL

The GDM-8261A can store and recall measurement history (for up to 9999 counts) as well as the instrument settings. For storing and recalling measurement results using the Scanner, see page 103.



Store Measurement Record 98
Recall Measurement Record 99
Save Instrument Settings 100
Recall Instrument Settings 101

Store Measurement Record

Background

The GDM-8261A can log up to 9999 measurement results (counts) which can be stored and recalled later for analysis. Basic measurement statistics such as Maximum, Minimum, Average value as well as Standard Deviation are also recorded with the data.

Note: Previously recorded measurements will be erased every time the store function is used or if power is reset.

Data count	2 ~ 9999

Not applicable to

Store/recall measurement history is not applicable to the Diode/Continuity tests ⇥/•)).

Store step

1. Press the Shift key followed by the DCI (Store) key. The store menu appears.



2. Move the cursor using the Left/Right key. Change the data count using the Up/Down key.



3. Press the Enter key to confirm editing and to go back to the previous display.



STO	Indicates the measurement history is stored

Recall Measurement Record

Background	The GDM-8261A can recall previously recorded measurement results for observation and analysis. The Standard Deviation, Maximum Value, Minimum Value and Average Value can also be viewed.
Not applicable to	Store/recall measurement history is not applicable to the Diode/Continuity tests ⊣/•)).
Recall stored record	Press the Shift key, then the ACI (Recall) key. The stored measurement record appears. 
1st display	Shows the stored measurement result
2nd display	Shows the reading count
RCL	Indicates the data has been recalled
View each reading	Change the reading count using the Up/Down key.
View Max/Min/ Average	Switch to the Standard Deviation/Average/Maximum/ Minimum value of the recorded data using the Right key. Use the left key to go back. 

Save Instrument Settings

Background

The GDM-8261A can save up to 5 instrument settings. The settings can save the state, function, I/O and range. Upon powering up, the current instrument setting is displayed.

Parameter	Save (1-5), Del-All

Saved Parameters

- Main display parameters
- 2nd display parameters
- Filter settings
- Beep settings
- I/O settings
- System Delay Time
- Backlight (Light) settings
- Math settings
- Auto-Zero settings
- Auto-Gain settings
- Scanner settings
- Settings for each function
- Continuity threshold
- TCO settings
- D-Shift
- Bandwidth
- Gate time
- RTD settings
- Input Resistance
- Input Jack
- I-DET
- TX TERM

Set Instrument Setting

1. Press the Shift key followed by the 2nd (Menu) key. The SYSTEM menu appears.



2. Press the Down key followed by the Right key three times. The Save menu appears.



3. Press the Down key to enter the Save menu.



1st display	Shows the memory number

4. Select the memory number using the Up/Down key or select Del-All to delete the save settings in memory.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to the default display.



Note The current instrument settings have been saved. To enable the settings at power up, follow the instructions in the next section.

Recall Instrument Settings

Background The Recall function enables saved settings or default settings to be recalled at the next power up or immediately.

Parameter	Recall (0-5), 0 = recall default settings
	P-ON: recall at next power up
	Now: recall right away

Recall Instrument Setting

1. Press the Shift key followed by the 2nd (Menu) key. The SYSTEM menu appears.



2. Press the Down key followed by the Left key three times. The Recall menu appears.





3. Press the Down key to enter the Recall menu.



1st display Shows the memory number

4. Select the memory number using the Up/Down key.

5. Press the Enter key to confirm your selection. Press the Exit key to go back to Recall menu.



6. Select the Now or P-ON option using the Up/Down key.

7. Press the Enter key to confirm your selection.

SCANNER (OPTIONAL)

The optional scanner, GDM-SC1, lets you effectively measure multiple channels connected to a single GDM-8261A DMM.





Installation	GDM-SC1 Scanner Specifications	104
	Configure Scanner	104
	Select Channel Group and Enable Scanner	106
	Connect Wires	107
	Insert Scanner	110
	Scanner Configuration Record	112
Setup	Overview	113
	Setup Simple Scan	114
	Setup Advanced Scan	116
	Use External Trigger	119
Run	Overview	120
	Run Scan/Step	120
	Recall Scan/Step Result	121
	Setup and Run Monitoring	121

GDM-SC1 Scanner Specifications

2-wire channel	16 pairs	Maximum current	2Arms (ch17, ch18)
4-wire channel	8 pairs	Resistance	2/4 wire
Single wire channel	N/A	Cold junction	N/A (internal)
Maximum voltage	250Vrms	Connection	Screw terminal

Scanner Installation

Configure Scanner

Open Scanner cover

1. Take off four screws from the bottom panel of the scanner.



2. Remove the top panel.



3. The connection terminals are revealed.


CARD INPUT LO
CARD INPUT HI
CARD SENSE LO
CARD SENSE HI
CH9 CH10 CH11 CH12 CH13 CH14 CH15 CH16
L H L H L H L H L H L H L H L H
H L H L H L H L H L H L H L H L
CH1 CH2 CH3 CH4 CH5 CH6 CH7 CH8
H L H L
CH17 CH18
AMPS LO
AMPS HI

Overview

16 general purpose channels are available, 8 on the left row, 8 on the right row. Current (ACI, DCI) measurement uses 2 extra channels. All channels are fully isolated (Hi and Lo).

Scan/Step connection

Refer to the below table for measurement and test line connections.

Item	No. of wires	No. of channels
DCV, ACV	2 wires (H, L)	16 (CH1 ~ 16)
DCI, ACI	2 wires (H, L)	2 (CH17, 18) (10A range only)
2W Resistance	2 wires (H, L)	16 (CH1 ~ 16)
4W Resistance	4 wires (Input H, L + Sense H, L)	8 pairs (CH1 [input]& 9[sense], 2&10,....8&16)
Diode/Continuity	2 wires (H, L)	16 (CH1 ~ 16)
Period/Frequency	2 wires (H, L)	16 (CH1 ~ 16)
Temp. (Thermocouple)	2 wires (H, L)	16 (CH1 ~ 16)

Temp. 2W RTD	2 wires (H, L)	16 (CH1 ~ 16)
Temp. 4W RTD	4 wires (Input H, L + Sense H, L)	8 pairs (CH1 [input]& 9[sense], 2&10,....8&16)

Select Channel Group and Enable Scanner

Background

16 channels are available for the scanner when using the GDM-8261A.

Group1	CH101 ~ 118

Select group (Jumper J8)

Set the jumper J8 in the center of the board to the MASTER configuration. Move the jumper to the right (pins 2-3) to select CH1xx (101 ~ 118). The GDM-8261A does not support the SLAVE operation mode with the optional scanner.



Enable scanner (Jumper J9)

Set the jumper J9 on the rear side of the board accordingly. Move the jumper up (pins 3-2) to disable the scanner, and down (pins 2-1) to enable the scanner.



Connect Wires

Wire selection

Make sure the wires have at least the same voltage and current capacity as the maximum ratings of the measurement.

Connection

1. Turn the screw left (loose) using a screw driver and insert the wire. Turn the screw right (tighten) and secure the connection.



2. Route the wires as shown below via the two openings (left and right) at the front cover.



Note

When using thermocouple wiring, please use extension wires so that the cold junction points are external to the scanner card. Connecting thermocouple wiring directly to the scanner box is not recommended due to the radiant heat from the internal components.



3. Bundle the wires at the front cover using the holes at the bottom.



4. Close the top cover and tighten the screw from the bottom.



Configuration Record	Print out the configuration record list on page 112, fill in the details, and keep it with the GDM-8261A.

Insert Scanner

Power Off

Turn the Power Off and take out the power cord.



Open the GDM-8261A rear panel slot

Take off the two screws on the slot corners to remove the optional slot cover. Keep the screws for later reuse.



Insert the scanner

Insert the scanner bottom-side-up (already configured according to the procedures on page 104) into the slot. Close the cover by tightening the screws.



Power On

Connect the power cord and turn On the power.



CAUTION Do not input voltages exceeding 250Vrms to the front input terminals while the scanner module is installed.

WARNING Do not connect any leads to the front input terminals while the scanner is active. Input signals scanned by the scan module also appear on the front terminals.

Scanner Configuration Record

Channel	Wire color		Measurement type	Note
CH1	H	L		
CH2	H	L		
CH3	H	L		
CH4	H	L		
CH5	H	L		
CH6	H	L		
CH7	H	L		
CH8	H	L		
CH9	H	L		
CH10	H	L		
CH11	H	L		
CH12	H	L		
CH13	H	L		
CH14	H	L		
CH15	H	L		
CH16	H	L		
CH17	H	L		
CH18	H	L		
CARD INPUT	H	L		
CARD SENSE	H	L		
AMPS	H	L		

Setup Scan

Overview

Scan type	Simple	Sets the scanned channel range, loop count, and timer length. All channels have a common measurement item.
	Advanced	In addition to the above Simple Scan settings, the advanced mode has custom settings for each channel, such as measurement item, range, and rate.
Timer setting	Sets the duration between each scan loop (Scan operation) or between each scanned channel (Step operation).	
Count setting	Sets the number of scan operations.	
Trigger setting	Internal (Continuous)	The GDM-8261A keeps triggering continuously until the scan reaches the end of the loop count. Then it goes into the idle mode.
	External (Manual)	The GDM-8261A stays in the idle mode by default. The trigger timing is manually controlled by the user from the front panel using the Trig key.
Scan operation	Scan	Measures all specified channel ranges (Channel MIN~MAX) for each trigger event. Timer settings (page 115) are applied between each scan for the whole channel range. Trigger delay settings are applied between each channel in each scan. For more detail about trigger delay setting, please refer to page 78.



Example: Scan channels 1~4 with a count setting of 12.

Step Measures a single channel in the specified range (Channel MIN~MAX)at each trigger event. Timer settings (page 115) apply for each channel.

- 

Example: Step through channel 1~4 with a count of 12.

Monitor Selects just one channel and continuously measures it.

Setup Simple Scan

Ensure the scanner has been installed before trying to configure the scanner (page 104).

Panel operation

1. Press the Shift key, the 2nd key (MENU), the Left key. The Scan menu appears.



2. Press the Down key. The Simple Scan menu appears.

3. Press the Down key again. The Starting (Minimum) channel setting appears.

4. Move the cursor to the channel using the Left/Right key, and change the value using the Up/Down key.



Range 101 ~ 118

5. When finished, press the Enter key. The End (Maximum) channel setting appears.

6. Move the cursor to the channel using the Left/Right key, and change the value using the Up/Down key.



Range 101 ~ 118, (must be equal to or greater than the Start (Min) channel)

7. When finished, press the Enter key. The Timer setting appears.

8. Move the cursor to the time setting using the Left/Right key, and change the value using the Up/Down key.



Range 1ms ~ 9999ms

9. Press the Enter key. The loop (step) Count setting appears.



10. Move the cursor to the count number using the Left/Right key, and change the value using the Up/Down key.



Range	1 ~ 999

11. Press the Enter key followed by the Exit key. The setting is stored and the display goes back to the normal mode.



Setup Advanced Scan

Panel operation

1. Press the Shift key, the 2nd key (MENU), the Left key. The Scan menu appears.



2. Press the Down key followed by the Right key. The Advanced Scan menu appears.



3. Press the Down key. The Starting (Minimum) channel setting appears.

4. Move the cursor to the channel using the Left/Right key, and change the value using the Up/Down key.



Range 101 ~ 118

5. When finished, press the Enter key. The End (Maximum) channel setting appears.

6. Move the cursor to the channel using the Left/Right key, and change the value using the Up/Down key.



Range 101 ~ 118 (must be greater than or equal to the Start (Min) channel)

7. When finished, press the Enter key. The Timer setting appears.

8. Move the cursor to the timer setting using the Left/Right key, and change the value using the Up/Down key.



Range 1ms ~ 9999ms

9. When finished, press the Enter key. The Count setting appears.



Range 1 ~ 999

10. Move the cursor to the count number using the Left/Right key, and change the value using the Up/Down key.



11. When finished, press the Enter key. The channel setting appears.

12. The Minimum (first) scanned channel appears. The default setting is CH101.



13. Set the measurement conditions.

- To select measurement item, press the target key.

- To select Auto range, press the AUTO key.



- To manually select the range, press the Up/Down key.

14. When finished, press the Right key to confirm the edit and to move to the next channel.

15. When all channel configurations are completed, press the Exit key followed by the ACV or DCV key. The display goes back to the default mode.



Use External Trigger

Background

The GDM-8261A uses the internal trigger by default. Using an external trigger allows customized triggering.

Signal connection

Connect the external trigger signal to the Digital I/O port located on the rear panel.



DB-9, female



Digital I/O pin assignment



Pin4	External Trigger Input pin

Activate external trigger

Press the Shift key followed by the Trig key. The EXT indicator appears on the display.



Start trigger

Press the Trig key to start triggering manually. The reading indicator (*) turns On.

Reading indicator

The reading indicator * stays On before triggering. After triggering, the indicator flashes according to the external signal trigger timing.

Exit external trigger

Press the Shift key followed by the Trig key. The EXT indicator disappears and the trigger goes back to the internal mode.



Run Scan

Overview

Scan operation type	Scan	Measures all the specified channel ranges at each trigger event. The timer settings (page 115) apply to each scan.
	Step	Measures a single channel in the specified range at each trigger event. The timer settings (page 115) apply to each channel.
	Monitor	Continuously measures one channel.

Run Scan/Step

Activate Scan/Step

1. Press the Shift key followed by the ACV key (Scan) or DCV key (Step).



2. The STO indicator turns On. The Scan (Step) starts running and the data is recorded. After running the predefined count, the Scan (Step) stops running.



Retrigger/Restart Scan

To run the Scan (Step) again, press the Trig key. The previous data is overwritten by the new Scan.

Abort Scan/Step

To abort Scan/Step or to go back to the normal display, press the Shift key followed by the ACV key (Scan) or DCV key (Step) again.



Recall Scan/Step Result

Panel operation

1. After the Scan/Step is completed, the data is stored internally. Press the Shift key followed by the ACI (Recall) key.



2. The first channel appears. (example: channel 101)



3. To view the Standard Deviation/Min/ Max/Average data, press the Left and Right keys.



4. To move to the next channel, press the Up/Down key.

5. Press the Exit key to get out from recall mode.

Setup and Run Monitoring

Panel operation

1. Press the Shift key, the 2nd (Menu) key, the Left key. The Scan menu appears.



2. Press the Down key followed by the Left key twice. The Monitor Scan setting menu appears.





3. Press the Down key. The channel selection appears.



4. Move the cursor to the channel using the Left/Right key, and change the channel number using the Up/Down keys.



5. When finished, press the Enter key. The Monitoring starts.



DIGITAL I/O

The rear panel Digital I/O terminal outputs the result of Compare measurements to external devices.



Terminal configuration	Digital I/O Terminal Configuration	124
Application	Application: Compare measurement	125
	Application: External trigger	128

Digital I/O Terminal Configuration

Background

The digital I/O terminal outputs the result of Compare measurements to control external devices. By providing separate VCC power for the terminal, the outputs can also be used as a power source for TTL and CMOS circuits.

Pin assignment

Connector type: DB-9 female





Pin1	VCC output, 5V. Serves as the unregulated max power source for the external device/logic. Without GPIB/LAN card: 4.5V/50mA With GPIB/LAN card: 4.0V/50mA
Pin2	NC (No Connection).
Pin3	Digital (chassis) Ground.
Pin4	External Trigger Input. Accepts external trigger signals. For using external signals, see page 119 (Scanner) or page 76 (Configuration).
Pin5-9	Pins 5-9 use open-collector outputs and thus require a pull-up resistor for each pin. The output resistor must have a minimum rating of 500Ω. All the outputs are active low.

Pins 5-9 output wiring diagram



Pin5	PASS signal Output. Activates when the compare result is PASS.
Pin6	FAIL signal Output. Activates when the compare result is FAIL.
Pin7	HIGH Limit FAIL signal Output. Activates when the compare result is FAIL due to violating the HIGH Limit.
Pin8	LOW Limit FAIL signal Output. Activates when the compare result is FAIL due to violating the LOW Limit.
Pin9	EOM (End Of Measurement) signal Output. Activates when compare measurement is over. It is also available in other measurements.

EOM pulse width timing



Application: Compare measurement

Applicable to	ACV DCV ACI DCI 2/4W Hz/P TEMP
Background	Compare measurement checks and updates if the measurement data stays between the upper (high) and lower (low) limit specified.
1. Activate Compare measurement	Press the Shift key, then the Hold (Comp) key. 
2. High limit setting	

1st display	Shows the high limit value
2nd display	Indicates high limit setting

1. Use the Left/Right key to move the cursor (flashing point) between high/low setting, digits, and decimal point. HOLD TRIG

2. Change the parameter using the Up/Down key.

3. Press the Enter key to confirm editing and move to the low limit setting.

3. Low limit setting

1st display	Shows the low limit value
2nd display	Indicates low limit setting

Set the low limit in the same way as in the high limit. Press the Enter key to confirm editing. The compare measurement starts right away.

4. Compare measurement appears

COMP	Indicates Compare mode
2nd display	Shows the compare measurement result: Pass, High, or Low.

5. Result

High	If the 2nd display shows High, the result is above the High limit.	
	Digital I/O: FAIL Out (Pin 6) and HIGH Limit FAIL Out (Pin 7) are activated.	
Low	If the 2nd display shows Low, the result is below the Low limit.	

		Digital I/O: FAIL Out (Pin 6) and LOW Limit FAIL Out (Pin 8) are activated.
	Pass	If the 2nd display shows Pass, the result is staying between the High and the Low limit. Digital I/O: PASS Out (Pin 5) is activated.
Timing Diagram for pins 5-8 when the Compare function is activated		
Deactivate Compare measurement	To cancel the Compare measurement, press the Shift key followed by the Hold (Comp) key, or simply activate another measurement.	

Application: External trigger

Background

The GDM-8261A uses the internal trigger by default, for example to count the frequency and the period. Using an external trigger allows for customized triggering conditions.

Signal connection

Connect the external trigger signal to the Digital I/O port located on the rear panel.



Pin4	External Trigger Input pin

Connection



Pulse width timing



1. Activate external trigger

Press the Shift key followed by the Trig key. The EXT indicator appears on the display.



2. Start trigger	Press the Trig key to start triggering manually. The * indicator turns On.	TRIG▶



Reading indicator	The reading indicator * stays On before triggering. After triggering, the indicator flashes according to the external signal trigger timing.	
Exit external trigger	Press the Shift key followed by the Trig key. The EXT indicator disappears and the trigger goes back to internal mode.	SHIFT / EXIT → INT/EXT TRIG▶

REMOTE CONTROL



Interface	Overview ..... 132 Configure USB Interface ..... 132 Configure RS-232C Interface ..... 133 Set the EOL Character ..... 134 Set the Separation Character ..... 135 Set the Return Format ..... 136 Insert GPIB Card ..... 138 Configure GPIB Interface ..... 139 Insert Ethernet Card ..... 141 Activate Ethernet Interface ..... 142 Configure Ethernet Interface (RESET) ..... 144 Configure Ethernet Interface to DHCP ..... 145 Configure Ethernet IP ..... 146 View MAC Address ..... 152 Configure Telnet Port ..... 153 Return to Initial Settings ..... 154 View Web Password Settings ..... 156 Remote Terminal Session (Telnet) 157
Web Control Interface	Web Control Interface 159
Command Syntax and Command Set	Command Syntax ..... 163 Command Set ..... 164 CONFigure Commands ..... 172 Secondary Display: CONFigure2 Commands ..... 174 Measure Commands ..... 177 SENSe Commands ..... 180 CALCulate Commands 194

TRIGger Commands 197
SYSTem Related Commands 200
STATus Report Commands 203
RS-232C Interface Commands 203
IEEE 488.2 Common Commands 203
ROUTe Commands 205

Configure Interface

Overview

Interface type	USB Device	USB 1.1 or 2.0, TypeA, female connector.
	RS-232C	D-sub 9 pin, male connector. Baud rate: 230400/115200/57600/38400/19200/9600. Data bits: 8, Parity: none, Stop bits: 1, Flow control: none.
	GPIB (optional)	24 Pin female GPIB port
	LAN (optional)	10BaseT/100BaseTx
Return to Local control mode	In order to switch back to the Local control mode (front panel operation), press the LOCAL key.	

Configure USB Interface

USB device port configuration

1. Press the Shift key, the 2nd (Menu) key, and then the left key repeatedly until the I/O configuration menu appears.



2. Press the Down key and the left key repeatedly until the USB selection display appears.



3. Press the Down key. The USB ON/OFF selection appears.



4. Press the Up/Down key to select ON or OFF.

5. Press the Enter key followed by the Exit key. The USB setting is stored and the display goes back to the default display.



6. Connect the USB cable to the rear panel terminal (upper port).

Configure RS-232C Interface

Configuration step

1. Press the Shift key, the 2nd (Menu) key, and then the left key repeatedly until the I/O configuration menu appears.



2. Press the Down key and the left key repeatedly until the RS232 selection display appears.



3. Press Enter or Down to confirm RS232 selection.



4. Press the Down or UP keys repeatedly to select the baud rate.

230400⇔115200⇔57600⇔38400⇔19200⇔9600

5. Press the Enter key followed by the Exit key. The RS-232 setting is stored and the display goes back to the default display.



6. Connect the RS-232C cable to the rear panel terminal.



RS-232C pin assignment

Pin 2: RxD
Pin 3: TxD
Pin 5: GND
Pin 1, 4, 6 ~ 9: No Connection



PC – GDM RS-232C Connection

A null-modem connection, in which transmit (TxD) and receive (RxD) lines are cross-linked, is required.



Set the EOL Character

Description

The TX TERM configuration menu can set the end-of-line (EOL) character for return messages. The GPIB and LAN's EOL character is fixed as CR+LF.

NOTE

The EOL character that is sent from the PC to the DMM can be either CR, LF or CR+LF. The most common EOL character is CR+LF.

EOL	CR, LF, CR+LF (default = CR+LF)

Configuration

1. Press the Shift key, the 2nd (Menu) key, the left key repeatedly until the TX TERM configuration menu appears.



2. Press the Down key. The EOL menu appears.

3. Press the Down key. The EOL selection menu appears.

4. Press the Up/Down key to select the EOL character.



5. Press the Enter key followed by the Exit key. The EOL setting is stored and the display goes back to the default display.



Set the Separation Character

Description

The TX TERM configuration menu can set the separation character for multiple return measurement values, the GPIB's separation character is fixed as a comma. While the separation character for LAN can be either CR+LF or a comma.

Configuration

1. Press the Shift key, the 2nd (Menu) key, the left key repeatedly until the TX TERM configuration menu appears.



2. Press the Down key and then the Right key. The SEP selection display appears.



3. Press the Down key. The SEP selection menu appears.



4. Press the Up/Down key to select the separation character.

EOL(CR+LF/LF/CR)⇔COMMA

5. Press the Enter key followed by the Exit key. The SEP setting is stored and the display goes back to the default display.



Set the Return Format

Description

When the VAL1?, VAL2?, TRACe:DATA? and FETCh? queries are used, the return measurement format can be configured in one of four ways: V (value), V+U (value, unit), V+C (value, count#), V+U+C (value, unit, count#). See page 198 and 198 for usage examples.

Note: The READ? query will not return values based on the return format settings, see page 197 for details.

Format	Description	Example
V	Value	+0.503E-4
V+U	Value, Unit	+0.503E-4, V DC
V+C	Value, Count#	+0.503E-4, +00001#
V+U+C	Value, Unit, Count#	+0.503E-4, V DC, +00001#

Configuration

1. Press the Shift key, the 2nd (Menu) key, the left key repeatedly until the TX TERM configuration menu appears.



2. Press the Down key, the Left key. The FORMAT menu appears.



3. Press the Down key. The FORMAT selection menu appears.

4. Press the Up/Down key to select the Return format.

5. Press the Enter key followed by the Exit key. The return format setting is saved and the display goes back to the default display.



Insert GPIB Card

Power Off

Turn the Power Off and take out the power cord.



Open the GDM-8261A optional communication port

Take off the two screws on the slot corners to remove the optional communication port cover. Keep the screws for later reuse.



Insert the GPIB card

Insert the GPIB card into the slot. Close the cover by tightening the screws.



Power On

Connect the power cord and turn On the power.



Configure GPIB Interface

GPIB port configuration

1. Press the Shift key, the 2nd (Menu) key, and then the left key repeatedly until the I/O configuration menu appears.



2. Press the Down key and the Left key repeatedly until the GPIB selection display appears.

   Note: The GPIB menu will be selectable only when the GPIB card is installed.



3. Press the Down key. The GPIB ON/OFF selection appears.

4. Press the Up/Down key to select ON or OFF.

5. To continue to the GPIB address configuration, press the Enter key. The GPIB address configuration menu appears.

1st display	Shows the GPIB address.
2nd display	Indicates GPIB address setting

6. Change the address using the Left/Right and Up/Down keys.



Range	0~30 (Default = 15)

7. Press the Enter key followed by the Exit key. The GPIB setting is stored and the display goes back to the default display.



8. Connect the GPIB cable to the rear panel optional communication port after the GPIB card has been installed (page 134).



GPIB pin assignment

Pin	Signal	Pin	Signal
1	Data I/O 1	13	Data I/O 5
2	Data I/O 2	14	Data I/O 6
3	Data I/O 3	15	Data I/O 7
4	Data I/O 4	16	Data I/O 8
5	EOI	17	REN
6	DAV	18	Ground (DAV)
7	NRFD	19	Ground (NRFD)
8	NDAC	20	Ground (NDAC)



9	IFC	21	Ground (IFC)
10	SRQ	22	Ground (SRQ)
11	ATN	23	Ground (ATN)
12	SHIELD Ground	24	Single GND

Insert Ethernet Card

Power Off

Turn the Power Off and take out the power cord.



Open the GDM-8261A optional communication port

Take off the two screws on the slot corners to remove the optional communication port cover. Keep the screws for later reuse.



Insert the Ethernet card

Insert the Ethernet card into the slot. Close the cover by tightening the screws.



Power On

Connect the power cord and turn on the power.



Initialize

Execute the INIT function to initialize the LAN settings, see page 154 for details.

Activate Ethernet Interface

Ethernet(LAN) port activation

1. Press the Shift key, the 2nd (Menu) key, and then the Left key repeatedly until the I/O configuration menu appears.



2. Press the Down key and the Left key repeatedly until LAN selection display appears.



Note: The LAN menu will be selectable only when the LAN card is installed.

3. Press the Down key. The LAN ON/OFF selection appears.

4. Press the Up/Down key to select ON or OFF. ON will turn the LAN option on, OFF will turn the LAN option off.

Note: Ethernet configuration settings can only be edited when LAN is set to ON.

5. Press the Enter key followed by the Exit key. The Ethernet port is turned on/off and the display goes back to the previous display.



6. Connect the Ethernet cable to the rear panel Ethernet port after the Ethernet card has been installed (page 141).



Configure Ethernet Interface (RESET)

Background

The RESET command is used to reset the Ethernet card when new settings have been made. When the DHCP, IP, subnet, gateway or DNS settings have been edited, use the RESET command to validate the changes and reset the Ethernet card to the new configuration settings. New Ethernet configuration settings are only updated after the Ethernet card has been reset.

Ethernet port configuration

1. Press the Shift key, the 2nd (Menu) key, the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key. The RESET selection display appears.

3. Press the Down key. The RESET YES/NO selection appears.

4. Press the Up/Down key to select YES or NO. YES will reset the Ethernet card, NO will cancel resetting the card.

5. Press the Enter key followed by the Exit key. The Ethernet card will be reset after the exiting the menu system.



Note

After the exiting the configuration menu, the Ethernet card will reset. Resetting the Ethernet card takes approximately 5 to 10 seconds.

The continuity icon (•)) is used to indicate the status of the Ethernet card after it has been reset:

•)) (flashing): indicates that the Ethernet card is resetting

•)) (flashing → turns off): indicates that the Ethernet card has finished resetting.

•)) (flashing → stays on): indicates that the Ethernet card has finished resetting when the continuity function is active (see page 38).

Configure Ethernet Interface to DHCP

Background

The GDM-8261A supports DHCP to have an IP address and other configuration parameters automatically assigned by a DHCP server. If the DHCP server is absent, the Ethernet card will automatically assign an IP address between 169.254.1.0 and 169.254.254.255 using AUTO-IP configuration.

1. DHCP Configuration

1. Press the Shift key, the 2nd (Menu) key, the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key. The DHCP selection display appears.



3. Press the Down key. The DHCP ON/OFF selection appears.

4. Press the Up/Down key to select ON or OFF. ON will turn on DHCP, OFF will turn off DHCP.

5. Press the Enter key followed by the Exit key.



2. Reset LAN card

1. To make any changes take effect, set RESET to YES. See page 144 for details.

Configure Ethernet IP

Background

The GDM-8261A supports manually setting of the IP addresses, including the subnet mask, gateway and DNS.

1. Manual IP Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key twice. The IP selection display appears.



Note: The IP address can only be edited if DHCP is off.

3. Press the Down key. The IP address selection appears.

The IP address is divided in 4 groups; IP1:IP2:IP3:IP4. The cursor will be flashing on IP1 (indicated by "X").

4. Use the Left/Right keys to move the cursor to the IP1 value and select a digit.





5. Press the Up/Down key to edit the selected digit.



6. Press the Enter key to confirm and automatically go onto IP2.

7. Repeat steps 4 to 6 for IP2, IP3 and IP4.

8. Press the Exit key to exit from the configuration menu.

2. Subnet Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key repeatedly until the SUBNET selection display appears.



Note: The subnet mask can only be edited if DHCP is off.

3. Press the Down key. The SUBNET address selection appears.

The subnet address is divided in 4 groups; S1:S2:S3:S4. The cursor will be flashing on S1 (indicated by "X").

4. Use the Left/Right keys to move the cursor to the S1 value and select a digit.



5. Press the Up/Down key to edit the selected digit.



6. Press the Enter key to confirm and automatically go onto S2.

7. Repeat steps 4 to 6 for S2, S3 and S4.

8. Press the Exit key to exit from the configuration menu.

3. Gateway Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key repeatedly until the GATEWAY selection display appears.



Note: The gateway can only be edited if DHCP is off.

3. Press the Down key. The GATEWAY address selection appears.

The gateway address is divided in 4 groups; G1:G2:G3:G4. The cursor will be flashing on G1 (indicated by "X").

4. Use the Left/Right keys to move the cursor to the G1 value and select a digit.





5. Press the Up/Down key to edit the selected digit.



6. Press the Enter key to confirm and automatically go onto G2.

7. Repeat steps 4 to 6 for G2, G3 and G4.

8. Press the Exit key to exit from the configuration menu.



4. DNS Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key repeatedly until the DNS selection display appears.



Note: The DNS address can only be edited if DHCP is off.

3. Press the Down key. The DNS address selection appears.



The DNS address is divided in 4 groups; D1:D2:D3:D4. The cursor will be flashing on D1 (indicated by "X").

4. Use the Left/Right keys to move the cursor to the D1 value and select a digit.





5. Press the Up/Down key to edit the selected digit.



6. Press the Enter key to confirm and automatically go onto D2.

7. Repeat steps 4 to 6 for D2, D3 and D4.

8. Press the Exit key to exit from the configuration menu.

5. Reset LAN card

1. To make any changes take effect, set RESET to YES. See page 144 for details.

View MAC Address

View MAC Address

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and the Right key repeatedly until the MAC menu level appears.



3. Press the Down key. The MAC address appears.

4. Press the Exit key to exit from the configuration menu.

Configure Telnet Port

Background

The GDM-8261A can set the telnet port used for virtual private networks. By default the telnet port is set to port 23.

1.Telnet Port Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and then the Right key repeatedly until the TELNET selection display appears.



3. Press the Down key. The Telnet port appears.

4. Change the telnet port using the Left/Right and Up/Down keys.



Range 1~65535 (Default = 23)



5. Press the Enter key followed by the Exit key to confirm and exit the configuration menu.



Return to Initial Settings

Background

The INIT function is used to return the GDM-8261A back to the original LAN settings. This will also reset the web password back to 123456 if the password has been forgotten.

The INIT function should also be used after the Ethernet card is installed.

Default LAN settings

- DHCP: ON
- TELNET Port: 23
- TELNET timeout: 900 seconds
- WEB password: 123456
- UPNP: 6432
- Module name: G8261A-00000000 (where 00000000 is the serial number)

Return to Initial Settings

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and then the Right key repeatedly until the INIT selection display appears.



3. Press the Down key. The INIT NO/YES selection appears.

4. Press the Up/Down key to select NO or YES. YES will return the Ethernet settings back to the initial settings, NO will cancel returning to the initial settings.

5. Press the Enter key followed by the Exit key to confirm the settings and exit from the configuration menu.



Note

If the GDM-8261A is returned to the initial settings, a reset is performed automatically (page 144) after exiting the configuration menu.

Resetting the Ethernet card takes approximately 5 to 10 seconds.

The continuity icon (·») is used to indicate the status of the Ethernet card after it has been reset:

·» (flashing): indicates that the Ethernet card is resetting

·» (flashing → turns off): indicates that the Ethernet card has finished resetting.

·» (flashing → stays on): indicates that the Ethernet card has finished resetting when the continuity function is active (see page 38).

View Web Password Settings

Background

The web password is set to 123456 by default. Only the on/off setting of the web password can be viewed with the GDM-8261A. The web password can only be set from the web control page, see page 159 for details.

1. Web Password Configuration

1. Press the Shift key, the 2nd (Menu) key, and the Left key repeatedly until the SET LAN configuration menu appears.



Note: SET LAN will only be available after LAN has been activated in the I/O menu, see page 142.

2. Press the Down key and then the Left key. The WEB PW selection display appears.



3. Press the Down key. The WEB PW ON/OFF selection appears.



4. Press the Up/Down key to select ON or OFF. When set to ON a password is required to enter the browser control page, When set to OFF, a password is not required to enter the browser control page.

5. Press the Enter key followed by the Exit key to confirm the settings and exit from the configuration menu.



Note The web password is set to 123456 by default. Setting INIT to YES will reset the password back to the default password if the password has been forgotten.

Remote Terminal Session (Telnet)

Background A terminal application can be used to remotely control the GDM-8261A via the telnet protocol.

Operation

1. Establish a connection via the Ethernet port. Page 141, 142

2. Open a terminal program such as Hyper Terminal and enter the IP address and port number of the GDM-8261A.

3. Run this query via the terminal application:

   *idn?

   The command will return the instrument manufacturer, model number, serial number and firmware version in the following format:
   >GWInstek,GDM8261A,00000000,1.0

4. See page 163 for more details on remote commands.

Web Control Interface

The web control interface is accessible with the optional Ethernet card. The web control interface allows remote access over LAN using a Java-enabled web browser.

The web control interface allows a web browser to modify parameter settings, remotely operate, control and monitor the GDM-8261A with a virtual front panel that mimics the GDM-8261A front panel interface.

Telnet parameters can also be edited by using the web control interface so that applets such as HyperTerminal or Telnet can be used to monitor measurement readings, control settings and run programs utilizing the same remote control command set used with the RS232 remote control.

Background	Before trying to access the web browser control interface, please ensure your browser has JavaScript and Netbios enabled.
1. Connection	1. Configure the LAN interface and connect the GDM-8261A to the LAN. Page 141, 142 2. Enter the IP address of the GDM-8261A in the address field of the web browser. 3. If WEB PW (web password) is set to ON, a dialog box will appear prompting for a password. Key in the password (default password:123456). 4. The web control Welcome Page appears.


GW INSTEK Good Will Instrument Co., Ltd.
GDM-8261A 6 1/2 Digit Dual Measurement Multimeter
FEATURES
6 1/2 Digit Display : 1,200,000 counts
DCV Basic Accuracy : 0.0035%
Dual Measurement with Vacuum Fluorescent Display (VFD)
11 Measurement Functions & 10 Advanced Measurement Functions
High Resolution: Up to 100pA with DCI and 1nA with ACI Measurements
Temperature Measurement (RTD & Thermocouple) from -200°C ~ +1820°C
High Transmission Speed: Up to 2,400 readings/second through the USB interface
Standard Interfaces : USB, RS232C, Digital I/O
Optional Interfaces : GPIB or LAN
Optional Scanner Card : GDM-SC1 (Vx16ch, Ix2ch)
Free Various PC software : DMM Viewer , LabVIEW Driver
Welcome Page
Web Control
View & Modify Configuration
Contact us

GDM-8261A Welcome Page

Note

If the password dialog box or the Welcome Page fail to appear when WEB PW is set to ON, please ensure JavaScript and prompting for scripted windows are enabled in your web browser.

To show how to enable these settings, IE8 is used as an example:

To enable prompting for scripted windows, go to:

Tools>Internet Options>Security>Custom Level>Scripting>Allow websites to prompt for information using scripted windows>Enable

To enable JavaScript, go to:

Tools>Internet Options>Security>Custom Level>Scripting>Active scripting>Enable

2. Web Control

1. To start web control, click on the Web Control icon.

2. The virtual control panel appears.



3. All the basic panel operations using the virtual control panel are nearly identical to using the actual GDM-8261A, with a few notable exceptions:

- The scan function is not accessible.
- Store/recall is not accessible.
- MX+B, 1/X, REF%, STATS and Compare is not accessible.
- Sensor is not accessible.
- The filter is not accessible.
- The configuration menu is not accessible.
- The shift key + 2nd key is used to turn off REL, MAX, MIN, Hold, dB, dBm and 2nd functions.

3. View and Modify LAN Configuration

The current Ethernet settings can be viewed and modified from the web control interface. Settings that cannot be edited using the GDM-8261A front panel, such as the web password, can be edited from the web control interface.

1. To edit or view the current configuration settings, click on the View & Modify Configuration icon.

2. The configuration settings appear.

Miscellaneous Settings

Name:	G8261A-00000000
Firmware Revision:	1.00
IP Address:	192.168.31.3
MAC Address:	00-1a-b6-00-02-74

IP Address Selection

Address Type:	DHCP/AutoIP
Static IP Address:	192 . 168 . 0 . 1
Subnet Mask:	255 . 255 . 255 . 0
Default Gateway:	192 . 168 . 0 . 254
DNS:	0 . 0 . 0 . 0 , 0 . 0 . 0 . 0
	Update Settings

General Configuration Settings

Module Name:	G8261A-00000000
UPnP port number:	6432
Telnet port number:	23
Telnet Timeout:	900 seconds(0 for no timeout)
	Update Settings

Password Modify

Old Password:	(3-6 characters alpha-numeric)
New Password:	(3-6 characters alpha-numeric)
Confirm Password:	
	Modify

Restore Factory Defaults

Restore all options to their factory default states:	Restore Defaults

3. The View & Modify Configuration page allows you to:

   - View the instrument name, firmware revision of the Ethernet card, IP address and MAC address.
   - Set the IP address to DHCP or static.
   - Configure the module host name, UPnP port number, telnet port number and telnet timeout time.
   - Modify the web password.
   - Restore the Ethernet card to the factory default settings (equivalent to the INIT function).

Command Syntax

The commands are partially compatible with IEEE488.2 (1992) and SCPI (1994) standard. Commands are NON-case sensitive.

Example command		1: Command Header 2: Single space 3: Parameter 1 4: Comma (no space after comma) 5: Parameter 2
Parameter example	Boolean	Boolean logic: 0 or 1. Used for On (1) or Off (0) command.
	NR1	Integer: 0, 1, 2, 3.....
	NR2	Decimal number: 0.0, 0.1, 0.2,....
	NR3	Floating point number: 4.5e-1, 8.5e+1,...
	NRf	Any NR1,NR2 or NR3 value.
	MIN, MAX	The GDM-8261A automatically translates to the Minimum (min) or Maximum (max) value available.
	DEF	Default setting value.
Automatic parameter range selection	The GDM-8261A automatically translates the command parameter into the closest available value.	
	Example 1	CONF:VOLT:DC 1 (Sets the measurement item to DC Voltage and the range to 1V).
	Example 2	CONF:VOLT:DC 2 (Sets the measurement item to DC Voltage and the range to 2V). There is no 2V range so the GDM-8261A selects the closest range, 10V.
EOL	Marks the end of a command line. The following messages are in accordance with IEEE488.2 standard.	
	LF, CR,CR+LF	EOL, user configurable (excluding GPIB), see page 134.

Message Separator	EOL or ,	Command separator, user configurable (excluding GPIB), see page 135.
Square Brackets	[ ]	Square brackets denote function commands or parameters that can be omitted from the command or query. For example the query, [SENSe:]UNIT? can be expressed in 2 valid forms: [SENSe:]UNIT? or UNIT?

Command Set

CONFigure:VOLTage:DC 172
CONFigure:VOLTage:AC 172
CONFigure:CURRent:DC 172
CONFigure:CURRent:AC 172
CONFigure:RESistance 172
CONFigure:FRESistance 173
CONFigure:FREQuency 173
CONFigure:PERiod 173
CONFigure:CONTinuity 173
CONFigure:DIODe 173
CONFigure:TEMPerature:TCOuple 173
CONFigure:TEMPerature:FRTD 173
CONFigure:TEMPerature:RTD 174
CONFigure:FUNCtion? 174
CONFigure:RANGe? 174
CONFigure:AUTO 174
CONFigure:AUTO? 174
CONFigure2:VOLTage:DC 174
CONFigure2:VOLTage:AC 175
CONFigure2:CURRent:DC 175
CONFigure2:CURRent:AC 175
CONFigure2:RESistance 175
CONFigure2:FRESistance 175
CONFigure2:FREQuency 176
CONFigure2:PERiod 176
CONFigure2:OFF 176

CONFigure2:FUNCtion? 176
CONFigure2:RANGe? 176
CONFigure2:AUTO 176
CONFigure2:AUTO? 176
MEASure:VOLTage:DC? 177
MEASure:VOLTage:AC? 177
MEASure:CURRent:DC? 177
MEASure:CURRent:AC? 177
MEASure:RESistance? 177
MEASure:FRESistance? 178
MEASure:FREQuency? 178
MEASure:PERiod? 178
MEASure:CONTinuity? 178
MEASure:DIODe? 178
MEASure:TEMPerature:TCOuple? 178
MEASure:TEMPerature:FRTD? 179
MEASure:TEMPerature:RTD? 179
MEASure2:VOLTage:DC? 179
MEASure2:VOLTage:AC? 179
MEASure2:CURRent:DC? 179
MEASure2:CURRent:AC? 179
MEASure2:RESistance? 180
MEASure2:FRESistance? 180
MEASure2:FREQuency? 180
MEASure2:PERiod? 180
[SENSe:]TEMPerature:TCOuple:TYPE 180
[SENSe:]TEMPerature:TCOuple:TYPE? 180
[SENSe:]TEMPerature:RJUNction:SIMulated 181
[SENSe:]TEMPerature:RJUNction:SIMulated? 181
[SENSe:]TEMPerature:RTD:TYPE 181
[SENSe:]TEMPerature:RTD:TYPE? 181
[SENSe:]TEMPerature:RTD:ALPHa 181
[SENSe:]TEMPerature:RTD:ALPHa? 181
[SENSe:]TEMPerature:RTD:BETA 181
[SENSe:]TEMPerature:RTD:BETA? 181
[SENSe:]TEMPerature:RTD:DELTa 181
[SENSe:]TEMPerature:RTD:DELTa? 181
[SENSe:]TEMPerature:FRTD:TYPE 182

[SENSe:]TEMPerature:FRTD:TYPE? 182
[SENSe:]TEMPerature:FRTD:ALPHa 182
[SENSe:]TEMPerature:FRTD:ALPHa? 182
[SENSe:]TEMPerature:FRTD:BETA 182
[SENSe:]TEMPerature:FRTD:BETA? 182
[SENSe:]TEMPerature:FRTD:DELTa 182
[SENSe:]TEMPerature:FRTD:DELTa? 182
[SENSe:]DETector:RATE 182
[SENSe:]DETector:RATE? 182
[SENSe:]AVERage:TCONtrol 183
[SENSe:]AVERage:TCONtrol? 183
[SENSe:]AVERage:COUNt 183
[SENSe:]AVERage:COUNt? 183
[SENSe:]AVERage:WINDow 183
[SENSe:]AVERage:WINDow? 183
[SENSe:]AVERage:STATe 183
[SENSe:]AVERage:STATe? 183
[SENSe:]FILTer:STATe 184
[SENSe:]FILTer:STATe? 184
[SENSe:]FREQuency:APERture 184
[SENSe:]FREQuency:APERture? 184
[SENSe:]PERiod:APERture 184
[SENSe:]PERiod:APERture? 184
[SENSe:]FREQuency:INPutjack 184
[SENSe:]FREQuency:INPutjack? 184
[SENSe:]PERiod:INPutjack 184
[SENSe:]PERiod:INPutjack? 185
[SENSe:]DETector:BANDwidth 185
[SENSe:]DETector:BANDwidth? 185
[SENSe:]ZERO:AUTO 185
[SENSe:]ZERO:AUTO? 185
[SENSe:]GAIN:AUTO 185
[SENSe:]GAIN:AUTO? 185
[SENSe:]CONTinuity:THReshold 185
[SENSe:]CONTinuity:THReshold? 185
[SENSe:]CURRent:DETect 185
[SENSe:]CURRent:DETect? 186
[SENSe:]DIGital:SHIFt 186

[SENSe:]DIGital:SHIFt? 186
[SENSe:]UNIT 186
[SENSe:]UNIT? 186
[SENSe:]FUNCtion[1/2]? 186
[SENSe:]FUNCtion[1/2] 186
[SENSe:]VOLTage:DC:RANGe 186
[SENSe:]VOLTage:DC:RANGe? 187
[SENSe:]VOLTage:AC:RANGe 187
[SENSe:]VOLTage:AC:RANGe? 187
[SENSe:]CURRent:DC:RANGe 187
[SENSe:]CURRent:DC:RANGe? 187
[SENSe:]CURRent:AC:RANGe 187
[SENSe:]CURRent:AC:RANGe? 187
[SENSe:]RESistance:RANGe 187
[SENSe:]RESistance:RANGe? 187
[SENSe:]FRESistance:RANGe 188
[SENSe:]FRESistance:RANGe? 188
[SENSe:]FREQuency:VOLTage:RANGe 188
[SENSe:]FREQuency:VOLTage:RANGe? 188
[SENSe:]PERiod:VOLTage:RANGe 188
[SENSe:]PERiod:VOLTage:RANGe? 188
[SENSe:]VOLTage:DC:RANGe:AUTO 188
[SENSe:]VOLTage:DC:RANGe:AUTO? 188
[SENSe:]VOLTage:AC:RANGe:AUTO 188
[SENSe:]VOLTage:AC:RANGe:AUTO? 189
[SENSe:]CURRent:DC:RANGe:AUTO 189
[SENSe:]CURRent:DC:RANGe:AUTO? 189
[SENSe:]CURRent:AC:RANGe:AUTO 189
[SENSe:]CURRent:AC:RANGe:AUTO? 189
[SENSe:]RESistance:RANGe:AUTO 189
[SENSe:]RESistance:RANGe:AUTO? 189
[SENSe:]FRESistance:RANGe:AUTO 189
[SENSe:]FRESistance:RANGe:AUTO? 189
[SENSe:]FREQuency:VOLTage:RANGe:AUTO 190
[SENSe:]FREQuency:VOLTage:RANGe:AUTO? 190
[SENSe:]PERiod:VOLTage:RANGe:AUTO 190
[SENSe:]PERiod:VOLTage:RANGe:AUTO? 190
[SENSe:]VOLTage:DC:RESolution 190

[SENSe:]VOLTage:DC:RESolution? 190
[SENSe:]VOLTage:AC:RESolution 190
[SENSe:]VOLTage:AC:RESolution? 190
[SENSe:]CURRent:DC:RESolution 190
[SENSe:]CURRent:DC:RESolution? 191
[SENSe:]CURRent:AC:RESolution 191
[SENSe:]CURRent:AC:RESolution? 191
[SENSe:]RESistance:RESolution 191
[SENSe:]RESistance:RESolution? 191
[SENSe:]FRESistance:RESolution 191
[SENSe:]FRESistance:RESolution? 191
[SENSe:]CONTinuity:RESolution 191
[SENSe:]CONTinuity:RESolution? 191
[SENSe:]DIODe:RESolution 192
[SENSe:]DIODe:RESolution? 192
[SENSe:]TEMPerature:TCOuple:RESolution 192
[SENSe:]TEMPerature:TCOuple:RESolution? 192
[SENSe:]TEMPerature:FRTD:RESolution 192
[SENSe:]TEMPerature:FRTD:RESolution? 192
[SENSe:]TEMPerature:RTD:RESolution 192
[SENSe:]TEMPerature:RTD:RESolution? 192
[SENSe:]VOLTage:DC:NPLCycles 193
[SENSe:]VOLTage:DC:NPLCycles? 193
[SENSe:]CURRent:DC:NPLCycles 193
[SENSe:]CURRent:DC:NPLCycles? 193
[SENSe:]RESistance:NPLCycles 193
[SENSe:]RESistance:NPLCycles? 193
[SENSe:]FRESistance:NPLCycles 194
[SENSe:]FRESistance:NPLCycles? 194
CALCulate:FUNCtion 194
CALCulate:FUNCtion? 194
CALCulate:STATe 194
CALCulate:STATe? 194
CALCulate:MINimun? 194
CALCulate:MAXimun? 194
CALCulate:HOLD:REFerence 194
CALCulate:HOLD:REFerence? 195
CALCulate:REL:REFerence 195

	CALCulate:REL:REFerence? 195
	CALCulate:LIMit:LOWer 195
	CALCulate:LIMit:LOWer? 195
	CALCulate:LIMit:UPPer 195
	CALCulate:LIMit:UPPer? 195
	CALCulate:DB:REFerence 195
	CALCulate:DB:REFerence? 195
	CALCulate:DBM:REFerence 195
	CALCulate:DBM:REFerence? 195
	CALCulate:STORe:COUNt 196
	CALCulate:STORe:COUNt? 196
	CALCulate:AVERage:COUNt 196
	CALCulate:AVERage:COUNt? 196
	CALCulate:AVERage:MINimum? 196
	CALCulate:AVERage:MAXimum? 196
	CALCulate:AVERage:AVERage? 196
	CALCulate:AVERage:PTPeak? 196
	CALCulate:AVERage:SDEViation? 196
	CALCulate:MATH:MMFactor 197
	CALCulate:MATH:MMFactor? 197
	CALCulate:MATH:MBFactor 197
	CALCulate:MATH:MBFactor? 197
	CALCulate:MATH:PERCent 197
	CALCulate:MATH:PERCent? 197
	CALCulate:NULL:OFFSet 197
	CALCulate:NULL:OFFSet? 197
	READ? 197
	VAL1? 198
	VAL2? 198
	TRIGger:SOURce 198
	TRIGger:SOURce? 198
	TRIGger:DELay 198
	TRIGger:DELay? 198
	TRIGger:AUTO 198
	TRIGger:AUTO? 199
	SAMPle:COUNt 199
	SAMPle:COUNt? 199
	TRIGger:COUNt 199

TRIGger:COUNt? 199
TRACe:DATA? 199
TRACe:CLEar 199
SYSTem:BEEPer:STATe 200
SYSTem:BEEPer:STATe? 200
SYSTem:BEEPer:ERRor 200
SYSTem:BEEPer:ERRor? 200
SYSTem:ERRor? 200
SYSTem:VERSion? 200
SYSTem:DISPlay 200
SYSTem:DISPlay? 200
SYSTem:OUTPut:FORMat 200
SYSTem:OUTPut:FORMat? 201
SYSTem:OUTPut:EOF 201
SYSTem:OUTPut:EOF? 201
SYSTem:OUTPut:SEParate 201
SYSTem:OUTPut:SEParate? 201
SYSTem:SERial? 201
SYSTem:PARameter:SAVE 201
SYSTem:PARameter:LOAD 201
SYSTem:PARameter:LOAD? 201
SYSTem:SCPi:MODE 202
SYSTem:SCPi:MODE? 202
SYSTem:IDNStr 202
SYSTem:IDNStr? 202
STATus:QUEStionable:ENABle 203
STATus:QUEStionable:ENABle? 203
STATus:QUEStionable:EVENt? 203
STATus:PRESet 203
SYSTem:LOCal 203
SYSTem:REMote 203
SYSTem:RWLock 203
*CLS 203
*ESE? 203
*ESE 203
*ESR? 204
*IDN? 204
*OPC? 204

*OPC 204
*PSC? 204
*PSC 204
*RST 204
*SRE? 204
*SRE 204
*STB? 204
*TRG 204
ROUTe:CLOSe 205
ROUTe:OPEN:ALL 205
ROUTe:MULTiple:OPEN 205
ROUTe:MULTiple:STATe? 205
ROUTe:MULTiple:CLOSe 205
ROUTe:FUNCtion 205
ROUTe:FUNCtion? 205
ROUTe:CHANnel 206
ROUTe:CHANnel? 206
ROUTe:COUNt 206
ROUTe:COUNt? 206
ROUTe:DELay 206
ROUTe:DELay? 206
ROUTe:STATe? 206
ROUTe:ADVance 207
ROUTe:ADVance? 207
ROUTe:SCAN:COUNt? 207
ROUTe:SCAN:FINal 207
ROUTe:SCAN:FINal? 207
ROUTe:SCAN:BOX 207
ROUTe:SCAN:BOX? 207
INPut:IMPedance:AUTO 207
INPut:IMPedance:AUTO? 207
INITiate 207
FETCh? 208
DATA:POINts? 208

CONFigure Commands

CONFigure:VOLTage:DC

Sets measurement to DC Voltage on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: CONF:VOLT:DC 1,MAX
Sets the voltage range to 1 volt and the resolution to the maximum.

CONFigure:VOLTage:AC

Sets measurement to AC Voltage on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF:VOLT:AC
Sets the AC voltage range and resolution to auto range.

CONFigure:CURRent:DC

Sets measurement to DC Current on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF:CURR:DC 10e-3,DEF
Sets the DC current range to 10mA using the default resolution.

CONFigure:CURRent:AC

Sets measurement to AC Current on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: CONF:CURR:AC 10e-2,MAX
Sets the measurement mode to ACI with a 100mA range at the maximum resolution.

CONFigure:RESistance

Sets measurement to 2W Resistance on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: CONF:RES 10e3,MIN
Sets the range to 10kΩ with the lowest resolution.

CONFigure:FRESistance

Sets measurement to 4W Resistance on the first display and specifies the range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF:FRES 10e3,MAX
Sets the measurement mode to 4W with a range of 10kΩ at the maximum resolution.

CONFigure:FREQuency

Sets measurement to Frequency on the first display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF:FREQ MAX,MAX
Sets the frequency measurement range to max and the resolution to max.

CONFigure:PERiod

Sets measurement to Period on the first display and specifies the range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF:PER
Sets the DMM to period measurement using the previous range/resolution.

CONFigure:CONTinuity

Sets measurement to Continuity on the first display.
Parameter: None

CONFigure:DIODe

Sets measurement to Diode on the first display.
Parameter: None

CONFigure:TEMPerature:TCOuple

Sets measurement to Temperature thermocouple (T-CUP) on the first display.
Parameter: [None] | [Type(B | E | J | K | N | R | S | T)]
Example: CONF:TEMP:TCO J
Sets the measurement mode to TCO with a type J sensor.

CONFigure:TEMPerature:FRTD

Sets the measurement mode to 4W RTD measurement mode on the first display. Sets the sensor type.
Parameter: [None] | [Type(PT100 | D100 | F100 | PT385 | PT3916 | USER)]
Example: CONF:TEMP:FRTD PT100
Sets the sensor type to PT100 and sets the measurement mode to 4W RTD

CONFigure:TEMPerature:RTD

Sets the measurement mode to 2W RTD measurement mode on the first display. Sets the sensor type.
Parameter: [None] | [Type(PT100 | D100 | F100 | PT385 | PT3916 | USER)]
Example: CONF:TEMP:RTD PT100
Sets the sensor type to PT100 and sets the measurement mode to 2W RTD

CONFigure:FUNCtion?

Returns the current function on 1st display.
Return parameter: VOLT, VOLT:AC, CURR, CURR:AC, RES, FRES, FREQ, PER, TEMP:RTD, TEMP:FRTD, TEMP:TCO, DIOD, CONT

CONFigure:RANGe?

Returns the current range on 1st display.
Return Parameter:
DCV: 0 .1(100mV), 1(1V), 10(10V), 100(100V), 1000(1000V)
ACV: 0.1(100mV), 1(1V), 10(10V), 100(100V), 750(750V)
ACI: 0.001 (1mA), 0.01(10mA), 0.1(100mA), 1(1A), 10(10A)
DCI: 0.0001 (100μA), 0.001 (1mA), 0.01(10mA), 0.1(100mA), 1(1A), 10(10A)
RES: 10E+1(100Ω) 10E+2(1kΩ), 10E+3(10kΩ), 10E+4 (100kΩ), 10E+5(1MΩ), 10E+6(10MΩ), 10E+7(100MΩ)

CONFigure:AUTO

Sets Auto-Range on or off on the first display.
Parameter: ON | OFF
Example: CONF:AUTO ON

CONFigure:AUTO?

Returns the Auto-Range status of the function on the 1st display.
Return Parameter: 0|1, 1=Auto range, 0=Manual range

Secondary Display: CONFigure2 Commands

CONFigure2:VOLTage:DC

Sets measurement to DC Voltage on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:VOLT:DC 1,MAX
Sets the voltage range to 1 volt and the resolution to the maximum.

CONFigure2:VOLTage:AC

Sets measurement to AC Voltage on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:VOLT:AC
Sets the measurement mode to AC voltage.

CONFigure2:CURRent:DC

Sets measurement to DC Current on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:CURR:DC 10e-3,DEF
Sets the DC current range to 10mA using the default resolution on the second display.

CONFigure2:CURRent:AC

Sets measurement to AC Current on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:CURR:AC 10e-2,MAX
Sets the measurement mode to ACI with a 100mA range at the maximum resolution.

CONFigure2:RESistance

Sets measurement to 2W Resistance on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:RES 10e3,MIN
Sets the range to 10kΩ with the lowest resolution.

CONFigure2:FRESistance

Sets measurement to 4W Resistance on the second display and specifies the range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:FRES 10e3,MAX
Sets the measurement mode to 4W with a range of 10kΩ at the maximum resolution.

CONFigure2:FREQuency

Sets measurement to Frequency on the second display and specifies range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:FREQ MAX,MAX
Sets the frequency measurement range to max and the resolution to max.

CONFigure2:PERiod

Sets measurement to Period on the second display and specifies the range/resolution.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf> | MIN | MAX | DEF)]
Example: CONF2:PER
Sets the DMM to period measurement using the previous range/resolution.

CONFigure2:OFF

Turns the second display function off.
Parameter: None.

CONFigure2:FUNCtion?

Returns the current function on the second display.
Return parameter: VOLT, VOLT:AC, CURR, CURR:AC, RES, FRES, FREQ, PER, NON

CONFigure2:RANGe?

Returns the range of the current function on the second display.
Return parameter:
DCV: 0 .1(100mV), 1(1V), 10(10V), 100(100V), 1000(1000V)
ACV: 0.1(100mV), 1(1V), 10(10V), 100(100V), 750(750V)
ACI: 0.001 (1mA), 0.01(10mA), 0.1(100mA), 1(1A), 10(10A)
DCI: 0.001 (1mA), 0.01(10mA), 0.1(100mA), 1(1A), 10(10A)
RES: 10E+1(100Ω) 10E+2(1kΩ), 10E+3(10kΩ), 10E+4 (100kΩ), 10E+5(1MΩ), 10E+6(10MΩ), 10E+7(100MΩ)

CONFigure2:AUTO

Sets Auto-Range on or off on the 2nd display.
Parameter: ON | OFF
Example: CONF2:AUTO ON

CONFigure2:AUTO?

Returns the Auto-Range status of the function on the 2nd display.
Return Parameter: 0|1, 1=Auto range, 0=Manual range

Measure Commands

MEASure:VOLTage:DC?

Returns the DC voltage measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:VOLT:DC ?
>+0.488E-4
Returns the DC voltage measurement as 0.0488 mV.

MEASure:VOLTage:AC?

Returns the AC voltage measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:VOLT:AC ?
>+0.511E-3
Returns the AC voltage measurement as 0.511 mV.

MEASure:CURRent:DC?

Returns the DC current measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:CURR:DC ?
>+0.234E-4
Returns the DC current measurement as 0.0234 mA.

MEASure:CURRent:AC?

Returns the AC current measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:CURR:AC ?
> +0.387E-2
Returns the AC current measurement.

MEASure:RESistance?

Returns the 2W resistance measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:RES?
> +1.181372E+6
Returns the 2W measurement.

MEASure:FRESistance?

Returns the 4W resistance measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:FRES?
> +1.181372E+6
Returns the 4W measurement.

MEASure:FREQuency?

Returns the frequency measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:FREQ?
> +0.215029E+5
Returns the frequency (21.5 kHz).

MEASure:PERiod?

Returns the period measurement on the first display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS:PER? MAX
Returns the period at the maximum range.

MEASure:CONTinuity?

Returns the continuity measurement on the first display.
Example: MEAS:CONT?
Returns the continuity.

MEASure:DIODe?

Returns the diode measurement on the first display.
Example: MEAS:DIOD?
Returns the diode measurement.

MEASure:TEMPerature:TCOuple?

Returns the temperature for the selected thermocouple type on the first display.
Parameter:[NONE] | B | E | J | K | N | R | S | T
Example: MEAS:TEMP:TCO? J
> +0.26348E+2
Returns the temperature.

MEASure:TEMPerature:FRTD?

Returns the 4W RTD temperature for the selected sensor type on the first display.
Parameter:[NONE] | PT100 | D100 | F100 | PT385 | PT3916 | USER
Example: MEAS:TEMP:FRTD? PT100
> +0.20050E+5
Returns the temperature.

MEASure:TEMPerature:RTD?

Returns the 2W RTD temperature for the selected sensor type on the first display.
Parameter:[NONE] | PT100 | D100 | F100 | PT385 | PT3916 | USER
Example: MEAS:TEMP:RTD? PT100
> +0.20050E+5
Returns the temperature.

MEASure2:VOLTage:DC?

Returns the DC voltage measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:VOLT:DC ?
>+0.488E-4
Returns the DC voltage measurement as 0.0488 mV.

MEASure2:VOLTage:AC?

Returns the AC voltage measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:VOLT:AC ?
>+0.511E-3
Returns the AC voltage measurement as 0.511 mV.

MEASure2:CURRent:DC?

Returns the DC current measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:CURR:DC ?
>+0.234E-4
Returns the DC current measurement as 0.0234 mA.

MEASure2:CURRent:AC?

Returns the AC current measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:CURR:AC ?
> +0.387E-2
Returns the AC current measurement.

MEASure2:RESistance?

Returns the 2W resistance measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:RES?
> +1.181372E+6
Returns the 2W measurement.

MEASure2:FRESistance?

Returns the 4W resistance measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:FRES?
> +1.181372E+6
Returns the 4W measurement.

MEASure2:FREQuency?

Returns the frequency measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:FREQ?
> +0.215029E+5
Returns the frequency (21.5 kHz).

MEASure2:PERiod?

Returns the period measurement on the second display.
Parameter: [None] | [Range(<NRf> | MIN | MAX | DEF),Resolution(<NRf>| MIN | MAX | DEF)]
Example: MEAS2:PER? MAX
Returns the period at the maximum range.

SENSe Commands

[SENSe:]TEMPerature:TCOuple:TYPE

Sets thermocouple type.
Parameter: Type(B | E | J | K | N | R | S | T)
Example: SENS:TEMP:TCO:TYPE J
Sets the thermocouple to type J.

[SENSe:]TEMPerature:TCOuple:TYPE?

Returns the thermocouple type.
Return parameter: B, E, J, K, N, R, S, T

[SENSe:]TEMPerature:RJUNction:SIMulated

Set temperature simulation value.
Parameter: <NRf>(0.00 ~ 50.00)
Example: SENS:TEMP:RJUN:SIM 25.00
Sets the thermocouple junction temperature to 25˚C.

[SENSe:]TEMPerature:RJUNction:SIMulated?

Returns temperature simulation value.
Return parameter: <NR1> (+0000~+5000) ,where +0000=0.00˚C, +5000=50.00˚C

[SENSe:]TEMPerature:RTD:TYPE

Sets the 2W RTD sensor type.
Return parameter: Type(PT100 | D100 | F100 | PT385 | PT3916 | USER)
Example: SENS:TEMP:RTD:TYPE PT100
Sets the 2W RTD sensor to PT100

[SENSe:]TEMPerature:RTD:TYPE?

Returns the 2W RTD sensor type.
Return parameter: PT100, D100, F100, PT385, PT3916, USER

[SENSe:]TEMPerature:RTD:ALPHa

Sets the 2W RTD Alpha coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:RTD:ALPH 0.00385

[SENSe:]TEMPerature:RTD:ALPHa?

Returns the 2W RTD Alpha coefficient.

[SENSe:]TEMPerature:RTD:BETA

Sets the 2W RTD BETA coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:RTD:BETA 0.00495

[SENSe:]TEMPerature:RTD:BETA?

Returns the 2W RTD BETA coefficient.

[SENSe:]TEMPerature:RTD:DELTa

Sets the 2W RTD DELTa coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:RTD:DELT 0.0000568

[SENSe:]TEMPerature:RTD:DELTa?

Returns the 2W RTD DELTa coefficient.

[SENSe:]TEMPerature:FRTD:TYPE
Sets the 4W RTD sensor type.
Parameter: Type(PT100 | D100 | F100 | PT385 | PT3916 | USER)
Example: SENS:TEMP:FRTD:TYPE PT100
Sets the 4W RTD sensor to PT100

[SENSe:]TEMPerature:FRTD:TYPE?
Returns the 4W RTD sensor type.
Return parameter: PT100, D100, F100, PT385, PT3916, USER

[SENSe:]TEMPerature:FRTD:ALPHa
Sets the 4W RTD Alpha coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:FRTD:ALPH 0.00385

[SENSe:]TEMPerature:FRTD:ALPHa?
Returns the 4W RTD Alpha coefficient.

[SENSe:]TEMPerature:FRTD:BETA
Sets the 4W RTD BETA coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:FRTD:BETA 0.00495

[SENSe:]TEMPerature:FRTD:BETA?
Returns the 4W RTD BETA coefficient.

[SENSe:]TEMPerature:FRTD:DELTa
Sets the 4W RTD DELTa coefficient.
Parameter: <NRf> (0~10)
Example: SENS:TEMP:FRTD:DELT 0.0000568

[SENSe:]TEMPerature:FRTD:DELTa?
Returns the 4W RTD DELTa coefficient.

[SENSe:]DETector:RATE
Sets the detection rate (sample rate)
Parameter: RATE(S | M | F)
Example: SENS:DET:RATE S
Sets the rate to slow (S).

[SENSe:]DETector:RATE?
Returns the sample rate.
Return parameter: SLOW, MID, FAST

[SENSe:]AVERage:TCONtrol
Selects the digital filter.
Parameter: MOV | REP
Example: SENS:AVER:TCON MOV
Sets the digital filter to the Moving filter.

[SENSe:]AVERage:TCONtrol?
Returns the current digital filter type.
Return parameter: MOV (moving), REP (repeating)

[SENSe:]AVERage:COUNt
Sets the digital filter count.
Parameter: <NR1> (2 ~ 100) | MIN | MAX
Example: SENS:AVER:COUN 100
Sets the digital filter count number to 100.

[SENSe:]AVERage:COUNt?
Returns the digital filter count.
Return parameter: <NR1> (+002~+100)

[SENSe:]AVERage:WINDow
Selects a digital filter window
Parameters: 0.01 | 0.1 | 1 | 10 | NONE
Example: SENS: AVER: WIND 0.1
Sets the digital filter window to 0.1%

[SENSe:]AVERage:WINDow?
Return the current digital filter window value
Return parameters: 0.01, 0.1, 1, 10, NONE

[SENSe:]AVERage:STATe
Turns the digital filter On/Off.
Parameter: ON | OFF
Example: SENS:AVER:STAT ON
Turns the digital filter on.

[SENSe:]AVERage:STATe?
Returns the state of the digital filter (on or off).
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]FILTer:STATe
Turns the analog filter On/Off.
Parameter: ON | OFF
Example: SENS:FILT:STAT ON
Turns the analog filter on.

[SENSe:]FILTer:STATe?
Returns the state of the analog filter (on or off).
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]FREQuency:APERture
Sets the aperture time (gate time) for the frequency function (0.01=F, 0.1=M, 1=S).
Parameter: (0.01 | 0.1 | 1)
Example: SENS:FREQ:APER 0.01
Sets the gate time to 0.01 seconds.

[SENSe:]FREQuency:APERture?
Returns aperture time (gate time) for the frequency function.

[SENSe:]PERiod:APERture
Sets the aperture time (gate time) for the period function(0.01=F, 0.1=M, 1=S).
Parameter: <NRf>(0.01 | 0.1 | 1)
Example: SENS:PER:APER 0.1
Sets the gate time to 0.1 seconds for the period function.

[SENSe:]PERiod:APERture?
Returns the aperture time (gate time) for the period function.

[SENSe:]FREQuency:INPutjack
Assigns an input port for the frequency function.
Parameter: (0|1|2) 0=volt, 1=1A, 2=10A
Example: SENS:FREQ:INP 0
Sets the input jack to the Volt input port.

[SENSe:]FREQuency:INPutjack?
Returns the assigned input port used for the frequency function.
Return Parameter: VOLT, 1A, 10A

[SENSe:]PERiod:INPutjack
Assigns an input port for the period function.
Parameter: (0|1|2) 0=volt, 1=1A, 2=10A
Example: SENS:PER:INP 0
Sets the input jack to the Volt input port.

[SENSe:]PERiod:INPutjack?

Returns the assigned input port used for the period function.
Return Parameter: VOLT, 1A, 10A

[SENSe:]DETector:BANDwidth

Sets the AC bandwidth (AC filter).
Parameter: (3 | 20 | 200)
Example: SENS:DET:BAND 20
Sets the AC bandwidth to 20Hz.

[SENSe:]DETector:BANDwidth?

Returns the AC bandwidth.

[SENSe:]ZERO:AUTO

Sets the Auto zeroing mode to on, off or once only.
Parameter: ON | OFF | ONCE
Example: SENS:ZERO:AUTO ONCE
Sets the auto zeroing to once only.

[SENSe:]ZERO:AUTO?

Returns the Auto zero mode.
Return Parameter: 0|1, 1=ON, 0=OFF

[SENSe:]GAIN:AUTO

Sets the Auto gain mode to on, off or once only.
Parameter: ON | OFF | ONCE
Example: SENS:GAIN:AUTO OFF
Turns the Auto gain mode off.

[SENSe:]GAIN:AUTO?

Returns the Auto gain mode.
Return parameter: 0|1, 1=ON, 0=OFF

[SENSe:]CONTinuity:THReshold

Sets the continuity threshold in ohms.
Parameter: <NRf> (0 ~ 1000)
Example: SENS:CONT:THR 500
Sets the continuity threshold to 500

[SENSe:]CONTinuity:THReshold?

Returns the continuity threshold.

[SENSe:]CURRent:DETect

Sets the current auto-detect mode on or off for the current functions.
Parameter: ON | OFF
Example: SENS:CURR:DET ON
Turns the current auto-detect on for the current function.

[SENSe:]CURRent:DETect?

Returns the auto-detect status for the current functions.
Return Parameter: 0|1 1=ON, 0=OFF

[SENSe:]DIGital:SHIFt

Sets the Digital Shift function on or off.
Parameter: ON | OFF
Example: SENS:DIG:SHIF ON
Turn the digital shift function on.

[SENSe:]DIGital:SHIFt?

Returns the Digital Shift function status.
Return Parameter: 0|1 1=ON, 0=OFF

[SENSe:]UNIT

Sets the temperature unit.
Parameter: C|F
Example: SENS:UNIT C
Sets the temperature unit to ˚C.

[SENSe:]UNIT?

Returns the temperature unit.

[SENSe:]FUNCtion[1/2]?

Returns the function displayed on the first or second display.
Return parameter:
(display 1): VOLT, VOLT:AC, CURR, CURR:AC, RES, FRES, FREQ, PER, TEMP:RTD, TEMP:FRTD, TEMP:TCO, DIOD, CONT
(display 2): VOLT, VOLT:AC, CURR, CURR:AC, RES, FRES, FREQ, PER, NON

[SENSe:]FUNCtion[1/2]

Sets the function for the first or second display.
Parameter:
(display1):"VOLT[:DC]", "VOLT:AC", "CURR[:DC]", "CURR:AC", "RES", "FRES", "FREQ", "PER", "TEMP:RTD", "TEMP:FRTD", "TEMP:TCO", "DIOD", "CONT"
(display2): "VOLT[:DC]", "VOLT:AC", "CURR[:DC]", "CURR:AC", "RES", "FRES", "FREQ", "PER", "NON"
Example: SENS:FUNC1 "VOLT:DC"
Sets the 1st display to the DCV function.

[SENSe:]VOLTage:DC:RANGe

Sets the DC Voltage measurement range.
Parameter: (<NRf> | MIN | MAX)
Example: SENS:VOLT:DC:RANG MIN
Set the DC voltage range to lowest range allowed.

[SENSe:]VOLTage:DC:RANGe?

Returns the DC Voltage measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]VOLTage:AC:RANGe

Sets the AC Voltage measurement range.
Parameter: (<NRf> | MIN | MAX)
Example: SENS:VOLT:AC:RANG MIN
Set the AC voltage range to lowest range allowed.

[SENSe:]VOLTage:AC:RANGe?

Returns the AC Voltage measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]CURRent:DC:RANGe

Sets the DC Current measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:CURR:DC:RANG 10 e-2
Sets the DC current range to 100mA.

[SENSe:]CURRent:DC:RANGe?

Returns the DC Current measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]CURRent:AC:RANGe

Sets the AC Current measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:CURR:AC:RANG 10 e-2
Sets the AC current range to 100mA.

[SENSe:]CURRent:AC:RANGe?

Returns the AC Current measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]RESistance:RANGe

Sets the 2W resistance measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:RES:RANG 1000
Sets the resistance range to 1kΩ.

[SENSe:]RESistance:RANGe?

Returns the 2W resistance measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]FRESistance:RANGe
Sets the 4W resistance measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:FRES:RANG 1000
Sets the 4W resistance range to 1kΩ.

[SENSe:]FRESistance:RANGe?
Returns the 4W resistance measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]FREQuency:VOLTage:RANGe
Sets the frequency measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:FREQ:VOLT:RANG MIN
Sets the frequency to the minimum frequency range.

[SENSe:]FREQuency:VOLTage:RANGe?
Returns the frequency measurement range.
Parameter: [None] | [MIN | MAX]

[SENSe:]PERiod:VOLTage:RANGe
Sets the period measurement range.
Parameter: Range(<NRf> | MIN | MAX)
Example: SENS:PER:VOLT:RANG MIN
Sets the period to the minimum range.

[SENSe:]PERiod:VOLTage:RANGe?
Returns the period measurement range.
Return parameter: [None] | [MIN | MAX]

[SENSe:]VOLTage:DC:RANGe:AUTO
Sets the DC voltage Auto range on/off.
Parameter: ON | OFF
Example: SENS:VOLT:DC:RANG:AUTO ON
Turns Auto-range on for DC voltage measurements.

[SENSe:]VOLTage:DC:RANGe:AUTO?
Returns the DC voltage Auto-range settings.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]VOLTage:AC:RANGe:AUTO
Sets the AC voltage Auto range on/off.
Parameter: ON|OFF
Example: SENS:VOLT:AC:RANG:AUTO ON
Turns Auto-range on for AC voltage measurements.

[SENSe:]VOLTage:AC:RANGe:AUTO?
Returns the AC voltage Auto-range settings.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]CURRent:DC:RANGe:AUTO
Sets the DC Current Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:CURR:DC:RANG:AUTO OFF
Turns Auto-range off for DC current measurements.

[SENSe:]CURRent:DC:RANGe:AUTO?
Returns the DC current Auto-range settings.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]CURRent:AC:RANGe:AUTO
Sets the AC Current Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:CURR:AC:RANG:AUTO OFF
Turns Auto-range off for AC current measurements.

[SENSe:]CURRent:AC:RANGe:AUTO?
Returns the AC current Auto-range settings.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]RESistance:RANGe:AUTO
Sets the 2W resistance Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:RES:RANG:AUTO ON
Turns Auto-range on for 2W resistance measurements.

[SENSe:]RESistance:RANGe:AUTO?
Returns the 2W resistance Auto-range setting.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]FRESistance:RANGe:AUTO
Sets the 4W resistance Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:FRES:RANG:AUTO ON
Turns Auto-range on for 4W resistance measurements.

[SENSe:]FRESistance:RANGe:AUTO?
Returns the 4W resistance Auto-range setting.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]FREQuency:VOLTage:RANGe:AUTO
Sets the Frequency Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:FREQ:VOLT:RANG:AUTO ON
Turns the Auto-range on for the frequency function.

[SENSe:]FREQuency:VOLTage:RANGe:AUTO?
Returns the frequency Auto-range setting.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]PERiod:VOLTage:RANGe:AUTO
Sets the Period Auto-range settings on/off.
Parameter: ON|OFF
Example: SENS:PER:VOLT:RANG:AUTO OFF
Turns the Auto-range setting off for period measurements.

[SENSe:]PERiod:VOLTage:RANGe:AUTO?
Returns the Period Auto-range setting.
Return parameter: 0|1, 0=OFF, 1=ON

[SENSe:]VOLTage:DC:RESolution
Sets the DC Voltage measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:VOLT:DC:RES MAX
Sets the DC Voltage resolution to MAX.

[SENSe:]VOLTage:DC:RESolution?
Returns the DC Voltage resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]VOLTage:AC:RESolution
Sets the AC Voltage measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:VOLT:AC:RES MAX
Sets the AC Voltage resolution to MAX.

[SENSe:]VOLTage:AC:RESolution?
Returns the AC Voltage resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]CURRent:DC:RESolution
Sets the DC Current measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:CURR:DC:RES 0.01
Sets the DC Current resolution to 0.01

[SENSe:]CURRent:DC:RESolution?

Returns the DC Current resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]CURRent:AC:RESolution

Sets the AC Current measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:CURR:AC:RES 0.0001
Sets the AC Current resolution to 0.0001

[SENSe:]CURRent:AC:RESolution?

Returns the AC Current resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]RESistance:RESolution

Sets the 2W Resistance measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:RES:RES 0.01
Sets the 2W Resistance resolution to 0.01

[SENSe:]RESistance:RESolution?

Returns the 2W Resistance resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]FRESistance:RESolution

Sets the 4W Resistance measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:FRES:RES 0.01
Sets the 4W Resistance resolution to 0.01

[SENSe:]FRESistance:RESolution?

Returns the 4W Resistance resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]CONTinuity:RESolution

Sets the Continuity measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:CONT:RES 0.001
Sets the Continuity resolution to 0.001

[SENSe:]CONTinuity:RESolution?

Returns the Continuity measurement resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]DIODe:RESolution

Sets the Diode measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example:SENS:DIOD:RES 0.1e-4
Sets the Diode resolution to 0.00001

[SENSe:]DIODe:RESolution?

Returns the Diode measurement resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]TEMPerature:TCOuple:RESolution

Sets the thermocouple (T-CUP) measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:TEMP:TCO:RES MAX
Sets the thermocouple resolution to the maximum.

[SENSe:]TEMPerature:TCOuple:RESolution?

Returns the thermocouple measurement resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]TEMPerature:FRTD:RESolution

Sets the 4W RTD measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:TEMP:FRTD:RES MAX
Sets the 4W RTD resolution to the maximum.

[SENSe:]TEMPerature:FRTD:RESolution?

Returns the 4W RTD measurement resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]TEMPerature:RTD:RESolution

Sets the 2W RTD measurement resolution. The resolution depends on the rate and range settings.
Parameter: Resolution(<NRf> | MIN | MAX)
Example: SENS:TEMP:RTD:RES MAX
Sets the 2W RTD resolution to the maximum.

[SENSe:]TEMPerature:RTD:RESolution?

Returns the 2W RTD measurement resolution.
Parameter: [None] | [MIN | MAX]

[SENSe:]VOLTage:DC:NPLCycles

Sets the integration time for DC Voltage measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds. For any <NRf> parameter, the DMM will automatically set the PLC to the closest acceptable PLC value (0.025, 0.1, 0.25, 1, 2, 12).
Parameter: NPLCycles(<NRf> | MIN | MAX)
Example: SENS:VOLT:DC:NPLC 12
Sets the integration time to 12 PLCs for DC Voltage.

[SENSe:]VOLTage:DC:NPLCycles?

Returns the integration time for DC Voltage measurement in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds.
Return parameter: 0.025, 0.1, 0.25, 1, 2, 12

[SENSe:]CURRent:DC:NPLCycles

Sets the integration time for DC Current measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds. For any <NRf> parameter, the DMM will automatically set the PLC to the closest acceptable PLC value (0.025, 0.1, 0.25, 1, 2, 12).
Parameter: NPLCycles(<NRf> | MIN | MAX)
Example: SENS:CURR:DC:NPLC 2
Sets the integration time to 2 PLCs for DC Current.

[SENSe:]CURRent:DC:NPLCycles?

Returns the integration time for DC Current measurement in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds.
Return parameter: 0.025, 0.1, 0.25, 1, 2, 12

[SENSe:]RESistance:NPLCycles

Sets the integration time for 2W resistance measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds. For any <NRf> parameter, the DMM will automatically set the PLC to the closest acceptable PLC value (0.025, 0.1, 0.25, 1, 2, 12).
Parameter: NPLCycles(<NRf> | MIN | MAX)
Example: SENS:RES:NPLC MIN
Sets the integration time to 0.025 PLCs for 2W resistance measurements.

[SENSe:]RESistance:NPLCycles?

Returns the integration time for 2W resistance measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds.
Return parameter: 0.025, 0.1, 0.25, 1, 2, 12

[SENSe:]FRESistance:NPLCycles

Sets the integration time for 4W resistance measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds. For any <NRf> parameter, the DMM will automatically set the PLC to the closest acceptable PLC value (0.025, 0.1, 0.25, 1, 2, 12).
Parameter: NPLCycles(<NRf> | MIN | MAX)
Example: SENS:FRES:NPLC MAX
Sets the integration time to the maximum for 4W resistance measurements.

[SENSe:]FRESistance:NPLCycles?

Returns the integration time for 4W resistance measurements in PLCs (power line cycles). Where one PLC is equal to 16.6 milliseconds.
Return parameter: 0.025, 0.1, 0.25, 1, 2, 12

CALCulate Commands

CALCulate:FUNCtion

Sets the Advanced function.
Parameter: OFF | MIN | MAX | HOLD | REL | COMP | DB | DBM | STORE | AVER | MXB | INV | REF
Example: CALC:FUNC REL
Sets the Advanced function to REL (relative)

CALCulate:FUNCtion?

Returns the current Advanced function.

CALCulate:STATe

Turns the Advanced function on/off.
Parameter: ON|OFF
Example: CALC:STAT OFF
Turns the Advanced function off.

CALCulate:STATe?

Returns the status of the Advanced function.
Return Parameter: 0 | 1, 1=ON, 0=OFF

CALCulate:MINimun?

Returns the minimum value from the Max/Min measurement.

CALCulate:MAXimun?

Returns the maximum value from the Max/Min measurement.

CALCulate:HOLD:REFerence

Sets the percentage threshold for the Hold function.
Parameter: <NRf> (0.01, 0.1, 1, 10)
Example: CALC:HOLD:REF 10
Sets the hold percentage to 10%.

CALCulate:HOLD:REFerence?
Returns the percentage threshold from the Hold function.

CALCulate:REL:REFerence
Sets the reference value for the relative function.
Parameter: <NRf> | MIN | MAX
Example: CALC:REL:REF MAX
Sets the reference value to the maximum allowed.

CALCulate:REL:REFerence?
Returns the reference value from the relative function.

CALCulate:LIMit:LOWer
Sets the lower limit of the compare function.
Para meter: <NRf> | MIN | MAX
Example: CALC:LIM:LOW 1.0
Sets the lower limit to 1.0

CALCulate:LIMit:LOWer?
Returns the lower limit of the compare function.

CALCulate:LIMit:UPPer
Sets the upper limit of the compare function.
Para meter: <NRf> | MIN | MAX
Example: CALC:LIM:UPP 1.0
Sets the upper limit to 1.0

CALCulate:LIMit:UPPer?
Returns the upper limit of the compare function.

CALCulate:DB:REFerence
Sets the reference value for the dB function.
Parameter: <NRf> | MIN | MAX
Example: CALC:DB:REF MAX
Sets the reference voltage for dB measurements to the maximum allowed.

CALCulate:DB:REFerence?
Returns the reference voltage from the dB function.

CALCulate:DBM:REFerence
Sets the resistance value for the dBm function.
Parameter: <NRf> | MIN | MAX
Example: CALC:DBM:REF MAX
Sets the resistance value for dBm measurements to the maximum allowed.

CALCulate:DBM:REFerence?
Returns the resistance value from the dBm function.

CALCulate:STORe:COUNt

Set the number of measurement counts that are recorded with the Store measurement function.
Parameter: <NR1> (2 ~ 9999) | MIN | MAX
Example: CALC:STOR:COUN 1000
Sets the number of counts to be recorded as 1000.

CALCulate:STORe:COUNt?

Returns the number of counts that are recorded with the Store measurement function.
Parameter: [None] | MIN | MAX

CALCulate:AVERage:COUNt

Sets the total number of statistic counts.
Parameter: <NR1> (0, 2~100000) 0=continuous count, 2~100000=count
Example: CALC:AVER:COUN 0
Sets the count to continuous.

CALCulate:AVERage:COUNt?

Returns the total number of recorded counts. The setting commands for this query are: CALCulate:STORe:COUNt, ROUTe:COUNt and CALCulate:AVERage:COUNt.
Parameter: None | <NR1> (0~2) 0=Store, 1=Scan, 2=Stats
Example: CALC:AVER:COUN? 0
>+0010
Returns the total number of counts set for the Store function (10 counts).

CALCulate:AVERage:MINimum?

Returns the minimum recorded value.
Parameter: None | <NR1>(0~2) 0=Store, 1=Scan, 2=Stats

CALCulate:AVERage:MAXimum?

Returns the maximum recorded value.
Parameter: None | <NR1>(0~2) 0=Store, 1=Scan, 2=Stats

CALCulate:AVERage:AVERage?

Returns the average recorded value.
Parameter: None | <NR1> (0~2) 0=Store, 1=Scan, 2=Stats

CALCulate:AVERage:PTPeak?

Returns the recorded peak to peak value (max value – min value).
Parameter: None | <NR1> (0|1|2) 0=Store, 1=Scan, 2=Stats
Return Parameter: <NRf>

CALCulate:AVERage:SDEViation?

Returns the recorded Standard Deviation.
Parameter: None | <NR1> (0~2) 0=Store, 1=Scan, 2=Stats

CALCulate:MATH:MMFactor
Sets the scale factor M for math measurements.
Para meter: <NRf> | MIN | MAX
Example: CALC:MATH:MMF MIN
Sets the scale factor M to the minimum allowed value.

CALCulate:MATH:MMFactor?
Returns the scale factor M used in the math measurement.

CALCulate:MATH:MBFactor
Sets the offset factor B for math measurements.
Para meter: <NRf> | MIN | MAX
Example: CALC:MATH:MBF MIN
Sets the offset factor B to the minimum allowed value.

CALCulate:MATH:MBFactor?
Returns the offset factor B used in the math measurement.

CALCulate:MATH:PERCent
Sets the reference value for the Percent function.
Para meter: <NRf> | MIN | MAX
Example: CALC:MATH:PERC MAX
Sets the reference value for the Percent function to the maximum.

CALCulate:MATH:PERCent?
Returns the reference value setting for the Percent function.

CALCulate:NULL:OFFSet
Sets the reference value for the relative function. This command is analogous to the CALCulate:REL:REFerence command.
Parameter: <NRf> | MIN | MAX
Example: CALC:NULL:OFFS MAX
Sets the reference value to the maximum allowed.

CALCulate:NULL:OFFSet?
Returns the reference value from the relative function. This query is analogous to the CALCulate:REL:REFerence? query.

TRIGger Commands

READ?
Returns 1st and 2nd display value. The Read query will not return the unit or count number of the reading.

VAL1?

Returns the 1st display reading in the unit format specified in the Configuration menu (Return Format, page 136) or from the SYSTem:OUTPut:FORMat command (page 200).
Example: SAMP:COUN 100
VAL1?
>+0.333E-4,V DC
>+0.389E-4,V DC
> etc, for 100 counts.
Queries 100 counts of stored samples from the 1st display.

VAL2?

Returns the 2nd display reading in the unit format specified in the Configuration menu (Return Format, page 136) or from the SYSTem:OUTPut:FORMat command (page 200).
Example: SAMP:COUN 100
VAL2?
>+0.345E-4,V DC
>+0.391E-4,V DC
> etc, for 100 counts.
Queries 100 counts of stored samples from the 2nd display.

TRIGger:SOURce

Selects the trigger source.
Parameter: INT | EXT
Example: TRIG:SOUR INT
Sets the trigger source as internal.

TRIGger:SOURce?

Returns current trigger source.

TRIGger:DELay

Sets the trigger delay in milliseconds
Parameter: <NRf>(0 ~ 9999) | MIN | MAX
Example: TRIG:DEL MAX
Sets the trigger delay to the maximum.

TRIGger:DELay?

Returns the trigger delay time in milliseconds.
Parameter: None | MIN | MAX

TRIGger:AUTO

Turns Trigger Auto mode on/off.
Parameters: ON | OFF
Example: TRIG:AUTO OFF
Turns the Trigger Auto mode off.

TRIGger:AUTO?

Returns the Trigger Auto mode.
Return parameter: 0|1, 0=OFF, 1=ON

SAMPle:COUNt

Sets the number of samples.
Parameter: <NR1>(1 ~ 9999) | MIN | MAX
Example: SAMP:COUN 10
Sets the number of samples to 10.

SAMPle:COUNt?

Returns the number of samples.
Parameter: None | MIN | MAX

TRIGger:COUNt

Sets the number of trigger counts.
Parameter: <NR1>(1 ~ 9999) | MIN | MAX
Example: TRIG:COUN 10
Sets the number of trigger counts to 10.

TRIGger:COUNt?

Returns the number of trigger counts.
Parameter: None | MIN | MAX

TRACe:DATA?

Returns the buffer contents of the last logged/recorded measurements.

TRACe:CLEar

Clears the buffer contents.

SYSTem Related Commands

SYSTem:BEEPer:STATe
Selects the beeper mode; no beep, beep on fail and beep on pass.
Parameter: <NR1>(0 | 1 | 2) 0=no beep, 2=fail, 1=pass
Example: SYST:BEEP:STAT 0
Turns the beeper off.

SYSTem:BEEPer:STATe?
Returns the beeper mode.
Return parameter: Beep on Pass | Beep on Fail | No Beep

SYSTem:BEEPer:ERRor
Sets the beeper to sound on an SCPI error.
Parameter: ON | OFF
Example: SYST:BEEP:ERR ON
Allows the beeper to sound when an SCPI error occurs.

SYSTem:BEEPer:ERRor?
Returns the beeper error mode.
Return parameter: 0|1, 0=OFF, 1=ON

SYSTem:ERRor?
Returns the current system error, if any.

SYSTem:VERSion?
Returns system version.
Return Parameter: X.XX.

SYSTem:DISPlay
Turns the Display on/off.
Parameter: ON | OFF
Example: SYST:DISP ON
Turns the display on.

SYSTem:DISPlay?
Returns the status of the display
Return parameter: 0|1, 0=OFF, 1=ON

SYSTem:OUTPut:FORMat
Sets the output format for the VAL1?, VAL2?, TRACe:DATA? and FETC? queries. The measured value (V) can be set to be displayed with the measurement units (U) and/or with the count number (C).
Parameter: <NR1>(0 ~ 3) 0=V, 1=V+U, 2=V+C, 3=V+U+C
Example: SYST:OUTP:FORM 3

SYSTem:OUTPut:FORMat?

Returns the output format.
Return parameter: (0|1|2|3) (0=V, 1=V+U, 2=V+C, 3=V+U+C)

SYSTem:OUTPut:EOF

Sets the EOL character (CR+LF, LF, CR).
Parameter: <NR1>(0 | 1 | 2) (0=CR+LF, 1=LF, 2=CR)
Example: SYST:OUTP:EOF 0
Sets the EOL character as CR+LF.

SYSTem:OUTPut:EOF?

Returns the EOL character.
Return parameter: <NR1>(0 | 1 | 2) (0=CR+LF, 1=LF, 2=CR)

SYSTem:OUTPut:SEParate

Sets the command separation character.
Parameter: <Boolean>(0|1) (0=EOL, 1=,)
Example: SYST:OUTP:SEP 0
Sets the command separation character as the EOL character.

SYSTem:OUTPut:SEParate?

Returns the command separation character.
Return parameter: <Boolean>(0|1) (0=EOL, 1=,)

SYSTem:SERial?

Returns the serial number (eight characters/numbers)

SYSTem:PARameter:SAVE

Saves the system parameters into 1 of 5 memory slots.
Parameter: <NR1> (1~5)
Example: SYST:PAR:SAVE 1
Saves the system parameters to memory 1.

SYSTem:PARameter:LOAD

Load the system parameters from 1 of 6 memory locations.
Parameter: <NR1> (0~5) (0=Default settings, 1~5= memory number)
Example: SYST:PAR:LOAD 0
Loads the default system parameters.

SYSTem:PARameter:LOAD?

Returns the loaded system parameters.
Return parameter: <NR1> (0~5) (0=Default settings, 1~5= memory number)

SYSTem:SCPi:MODE

Sets the SCPI mode. The SCPI mode is used to determine whether the *IDN? query returns the “Normal” or “Compatible” identification string . See the SYSTem:IDNStr command for details.
Parameter: NOR | COMP (NOR=Normal, COMP= Compatible)
Example: SYST:SCP:MODE NOR
Sets the SCPI mode to normal.

SYSTem:SCPi:MODE?

Returns the SCPI mode. The SCPI mode is used to determine whether the *IDN? query returns the “Normal” or “Compatible” identification string . See the SYSTem:IDNStr command for details.
Return parameter: NORMAL | COMPATIBLE

SYSTem:IDNStr

Sets a user-defined identification string for the *IDN? query when the SYSTem:SCPi:MODE command is set to “Compatible”.
Parameter: <“manufacturer”>, <“model number”>
Example: SYST:IDNS “ADCDE”, “12345”
Sets the user-defined manufacturer as ABCDE and the model number as 12345.

SYSTem:IDNStr?

Returns the manufacturer and model number set with the SYSTem:IDNStr command.
Return parameter: manufacturer, model number
Example: SYST:IDNS?
>ABCDE, 12345
Returns the manufacturer as ABCDE and the model number as 12345.

STATus Report Commands

STATus:QUEStionable:ENABle
Set bits in the Questionable Data Enable register.

STATus:QUEStionable:ENABle?
Returns the contents of the Questionable Data Enable register.

STATus:QUEStionable:EVENt?
Returns the contents of the Questionable Data Event register.

STATus:PRESet
Clears the Questionable Data Enable register.
Example: STAT:PRES

RS-232C Interface Commands

SYSTem:LOCal
Enables local control (front panel control) and disables remote control.

SYSTem:REMote
Enables remote control and disables local control (front panel control)

SYSTem:RWLock
Enables remote control and disables local control (front panel control). This command is analogous to the SYSTem:REMote command.

IEEE 488.2 Common Commands

*CLS
Clears the Event Status register (Output Queue, Operation Event Status, Questionable Event Status, Standard Event Status)

*ESE?
Returns the ESER (Event Status Enable Register) contents.
Example: *ESE?
>130
Returns 130. ESER=10000010

*ESE
Sets the ESER contents.
Parameter: <NR1> (0~255)
Example: *ESE 65
Sets the ESER to 01000001

*ESR?

Returns SESR (Standard Event Status Register) contents.
Example: *ESR?
>198
Returns 198. SESR=11000110

*IDN?

Returns the manufacturer, model No., serial number and system version number.
Example: *IDN?
>GWInstek,GDM8261A,00000000,1.0

*OPC?

"1" is placed in the output queue when all the pending operations are completed.

*OPC

Sets operation complete bit (bit0) in SERS (Standard Event Status Register) when all pending operations are completed.

*PSC?

Returns power On clear status.
Return parameter: <Boolean>(0|1) 0= don't clear, 1=clear

*PSC

Clears power On status.
Parameter: <Boolean>(0|1) 0=don't clear, 1= clear

*RST

Recalls default panel setup.

*SRE?

Returns the SRER (Service Request Enable Register) contents.

*SRE

Sets SRER contents.
Parameter: <NR1>(0~255)
Example: *SRE 7
Sets the SRER to 00000111.

*STB?

Returns the SBR (Status Byte Register) contents.
Example:*STB?
>81
Returns the contents of the SBR as 01010001.

*TRG

Manually triggers the GDM-8261A.

ROUTe Commands

ROUTe:CLOSe

Close a specified scanner channel.
Parameter: <NR1>(101~118)
Example: ROUT:CLOS 102
Closes channel 102.

ROUTe:OPEN:ALL

Opens all scanner channels.

ROUTe:MULTiple:OPEN

Enable all channels in a specified range. Channels that are not in the range are not affected.
Parameter: <NR1>(101~118)
Example: ROUT:MULT:OPEN 105,110
Channels 105 to 110 are enabled.

ROUTe:MULTiple:STATe?

Returns the status of all the scanner channels that are open.
Return parameter: 101 OFF, 102 ON, 103 ON etc.

ROUTe:MULTiple:CLOSe

Disable channels in a specified range.
Parameter: <NR1> (101~118)
Example: ROUT:MULT:CLOS 105,110
Disables channels 105~110.

ROUTe:FUNCtion

Enables scan related functions
Parameter: OFF | SCAN | STEP
Example: ROUT:FUNC SCAN
Enables the SCAN function.

ROUTe:FUNCtion?

Returns the Scan related function status.

ROUTe:CHANnel

Advanced configuration mode for the scanner channels. The channel function, voltage and Auto-range mode can be configured.
Parameter: Channel(<NR1>), Function(String), Range(<NRf>), Auto Range(ON|OFF)
Function: 1(VOLT), 2(VOLT:AC), 3(CURR [DCI]), 4(CURR:AC [ACI]), 7(RES), 8(FREQ), 9(TEMP:TCO:C), 13(CONT), 14(PER), 15(TEMP:TCO:F), 16(FRES), 17(DIOD), 18(TEMP:RTD:C), 19(TEMP:FRTD:C), 20(TEMP:RTD:F), 21(TEMP:FRTD:F)
Range: <NRf>
Autorange: 0=Off, 1=On
Example: ROUT:CHAN 101,1,1,0
Sets channel 1 (101) to VOLT (1), 1V range (1) and disables Auto-range (0).

ROUTe:CHANnel?

Returns the advanced channel configuration settings of each channel. See the ROUTe:CHANnel command for return parameters.
Return parameter: Channel, Function, Range, Auto Range
Example: ROUT:CHAN? 101
> 101,VOLT,0.1,ON
Returns channel 101, function is VOLT with range at 0.1V and Auto range on.

ROUTe:COUNt

Set the number of counts for the scan.
Parameter: <NR1>(1 ~ 999) | MIN | MAX
Example: ROUT:COUN 50
Sets the scan count to 50 counts.

ROUTe:COUNt?

Returns the number of counts for the scan.
Parameter: None | MIN | MAX

ROUTe:DELay

Set the Delay timer for the scan in milliseconds.
Parameter: <NR3> (0 ~ 9999) | MIN | MAX
Example: ROUT:DEL 100
Sets the delay time to 100 milliseconds.

ROUTe:DELay?

Returns the Delay timer settings.
Parameter: None | MIN | MAX

ROUTe:STATe?

Queries whether the scanner box is installed or not.
Return parameter: Boolean(0|1) 0=not installed, 1=installed

ROUTe:ADVance

Turns the scanner Advanced mode on/off.
Parameter: ON|OFF
Example: ROUT:ADV OFF
Turns advanced scanner mode off.

ROUTe:ADVance?

Returns the advanced mode status (on/off).
Return parameter: <Boolean>(0|1) (0=OFF, 1=ON)

ROUTe:SCAN:COUNt?

Returns the current scan count number.
Return parameter: <NR1>(1~999)

ROUTe:SCAN:FINal

Configures the DMM to send a "SCAN OK" message at the completion of the scan.
Parameter: ON | OFF
Example: ROUT:SCAN:FIN ON
"SCAN OK" will be sent at the completion of the scan.

ROUTe:SCAN:FINal?

Returns the status of the ROUTe:SCAN:FINal command.
Return parameter: <Boolean>(0|1) (0=OFF, 1=ON)

ROUTe:SCAN:BOX

Sets type of scanner box (voltage/current).
Parameter: Volt | Curr
Example: ROUT:SCAN:BOX VOLT
Sets the scanner box type to voltage.

ROUTe:SCAN:BOX?

Returns the configured scanner box type.
Return parameter: VOLT | CURR

INPut:IMPedance:AUTO

Sets the Automatic input impedance for DCV mode.
Parameter: ON|OFF
Example: INP:IMP:AUTO ON
Turns the Automatic input impedance on.

INPut:IMPedance:AUTO?

Returns the Automatic input impedance mode.
Return parameter: <Boolean>(0|1) (0=OFF, 1=ON)

INITiate

Set the trigger system to wait-for-trigger mode and to store readings.

FETCh?

Transfer the stored readings to the output buffer.

DATA:POINts?

Returns the number of readings.
Parameter: None | <NR1> (0~2) 0=Store, 1=Scan, 2=Stats

For the following command sets, please refer to the status system diagram on page 217

STAT: QUES:EVEN?
STAT: QUES: ENAB
STAT: QUES: ENAB?
*ESR?
*ESE
*ESE?
*STB?
*SRE
*SRE?

FAQ

- I pressed the EXIT key but cannot get out of Scanner mode.
- The GDM-8261A performance does not match the specifications.

I pressed the EXIT key but cannot get out of Scanner mode.

Press the Exit key, followed by the ACV (Scan) or DCV (Step) key.

The GDM-8261A performance does not match the specifications.

Make sure the device is powered On for at least 1 hour. This is necessary to stabilize the unit to match the specifications.

How can I achieve the fastest measurement speed

To achieve the fastest measurement speed, the DMM must use the internal trigger and must also be used in remote control mode using the USB interface. The following settings should also be set remotely:

1. The measurement mode and/or range settings applicable for the measurement. For example:
   DCI:
   CONF:CURR:DC 1 (see page 175)
   SENS:CURR:DC:NPLC 0.025 (see page 193)
   DCV:
   CONF:VOLT:DC 1 (see page 172)
   SENS:VOLT:DC:NPLC 0.025 (see page 193)
   2W:
   CONF:RES 1000 (see page 175)
   SENS:RES:NPLC 0.025 (see page 193)
   4W:
   CONF:FRES 1000 (see page 175)
   SENS:FRES:NPLC 0.025 (see page 194)

2. SYST: DISP OFF

3. SYST: OUTP:FORM 0

4. TRIG:DEL 0

5. SENS:AVER:STAT OFF

6. SAMP:COUN 2400

7. VAL1 ?

If there is still a problem, please contact your local dealer or GWInstek at marketing@goodwill.com.tw.

APPENDIX

System Info	Firmware Version	212
Fuse Replacement	Replace AC Source Fuse	213
	Replace Input Current Fuse	214
Menu Tree	Menu Tree	215
Status system	Status system	217
Specifications	General	218
	DC Characteristics [3]	219
	AC Characteristics [1]	221
	Frequency and Period Characteristics	224
	Temperature Characteristics	225
	Dimensions	226
EC Declaration	EC Declaration of Conformity	227

Firmware Version

Background

Firmware version is available from the system menu.

Firmware version	Shows the GDM-8261A firmware version number.

View firmware version

1. Press the Shift key followed by the 2nd (Menu) key. The system menu appears.



2. Press the Down key followed by the Right key. The firmware version menu appears.



3. Press the Down key. The firmware version appears.

4. Press the Exit key to go back to the default display.

Fuse Replacement

Replace AC Source Fuse

Steps

1. Take off the power cord and remove the fuse socket using a minus driver.



2. Replace the fuse in the holder.



3. Ensure the correct line voltage is lined up with the arrow on the fuse holder. Insert the fuse socket.



Rating	0.315AT, 100/120VAC; 0.125AT, 220/240VAC

Replace Input Current Fuse

Step

1. Press the Fuse holder.



2. The fuse holder comes out. Replace the fuse inserted at the end of the holder.



Rating	T1.25A, 250V

Menu Tree

Menu Tree

Background

The menu tree diagram shown on the next page represents the configuration menu that is accessed by pressing the Shift key and 2ND (Menu) key. The menu tree is arranged as a three-level tree structure.

Menu Tree Navigation



Continued next page.

Configuration Menu Tree



Status system

The diagram below is a description of the status system



For the following command sets, please refer to the diagram above.

STAT: QUES: EVEN?
STAT: QUES: ENAB
STAT: QUES: ENAB?
*ESR?
*ESE
*ESE?
*STB?
*SRE
*SRE?

Specifications

General

Note	• All specifications are ensured only under a single display. • At least 1 hour of warm-up time is required before applying these specifications. • Make sure that the Sense LO terminal to COM port is limited to 100Vpk, the Sense HI to Sense LO terminals are limited to 200Vpk and the COM port to earth is limited to 500Vpk. CAT II 600V. MAX DC1000V, AC 750V
Power Supply	100 V / 120 V / 220 V / 240 V ±10%
Power Line Frequency	45 Hz to 66 Hz and 360 Hz to 440 Hz
Operating Environment	Full accuracy for 0°C to 55°C, Full accuracy to 80% R.H. at 40°C
Storage Environment	-40°C to 70°C
Power Consumption	Max 25VA
Dimensions	265 mm (W) X 107 mm (H) X 350 mm (D)
Weight	Approximately 3.1 kg

DC Characteristics [3]

DC Voltage [1]

Range [4]	24 Hour 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [6]
100.0000 mV	0.0030 + 0.0030	0.0040 + 0.0035	0.0050 + 0.0035	0.0005 + 0.0005
1.000000 V	0.0015 + 0.0004	0.0020 + 0.0005	0.0035 + 0.0005	0.0005 + 0.0001
10.00000 V	0.0020 + 0.0006	0.0030 + 0.0007	0.0048 + 0.0007	0.0005 + 0.0001
100.0000 V	0.0020 + 0.0006	0.0035 + 0.0006	0.0081 + 0.0006	0.0005 + 0.0001
1000.000 V	0.0025 + 0.0006	0.0044 + 0.0010	0.0090 + 0.0010	0.0005 + 0.0001

Accuracy Specifications: ± (% of reading + % of range)

Resistance [1] [4] [5]

Range [4]	Test Current	24 Hour 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [6]
100.0000 Ω	1 mA	0.0030 + 0.0030	0.008 + 0.004	0.010 + 0.004	0.0008 + 0.0005
1.000000 kΩ	1 mA	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0008 + 0.0001
10.00000 kΩ	100µA	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0008 + 0.0001
100.0000 kΩ	10µA	0.0020 + 0.0005	0.008 + 0.001	0.010 + 0.001	0.0008 + 0.0001
1.000000 MΩ	3.5µA	0.002 + 0.001	0.008 + 0.001	0.010 + 0.001	0.0010 + 0.0002
10.00000 MΩ	350nA	0.015 + 0.001	0.020 + 0.001	0.040 + 0.001	0.0030 + 0.0004
100.0000 MΩ	350 nA// 10 MΩ	0.300 + 0.010	0.800 + 0.010	0.800 + 0.010	0.1500 + 0.0002

Accuracy Specifications: ± (% of reading + % of range)

DC Current [1]

Range [4]	Burden Voltage	24 Hour 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [6]
100.0000 µA	< 0.015 V	0.01 + 0.02	0.04 + 0.025	0.05 + 0.025	0.002 + 0.0030
1.000000 mA	< 0.15 V	0.007 + 0.005	0.030 + 0.005	0.05 + 0.005	0.002 + 0.0005
10.00000 mA	< 0.07 V	0.005 + 0.010	0.030 + 0.020	0.05 + 0.020	0.002 + 0.0020
100.0000m A	< 0.7 V	0.01 + 0.004	0.030 + 0.005	0.05 + 0.005	0.002 + 0.0005
1.000000 A	< 0.8 V	0.05 + 0.006	0.080 + 0.010	0.100 + 0.010	0.005 + 0.0010
10.00000 A	< 0.5 V	0.10 + 0.008	0.120 + 0.008	0.15 + 0.008	0.005 + 0.0008

Accuracy Specifications: ± (% of reading + % of range)

Continuity [2] [7]

Range [4]	Test Current	24 Hour 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [6]
1000.000Ω	1 mA	0.002 + 0.030	0.008 + 0.030	0.010 + 0.030	0.001 + 0.002

Accuracy Specifications: ± (% of reading + % of range)

Diode Test [2] [7]

Range [4]	Test Current	24 Hour 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [6]
1.000000 V	1 mA	0.002 + 0.010	0.008 + 0.020	0.010 + 0.020	0.001 + 0.002

Accuracy Specifications: ± (% of reading + % of range)

Measuring Characteristics

DC Voltage	Input Resistance	Range	
		0.1V	10MΩ or >10GΩ Selectable
		1V	10MΩ or >10GΩ Selectable
		10V	11.11MΩ ±1%
		100V	10.1MΩ±1%
		1000V	10.1MΩ±1%
	Input Bias	30pA (Typ, 25°C)	
	Input Protection	1000V on all ranges	
Measurement Method: Sigma-delta A/D Converter			
Resistance	Max. Lead Resistance	10% of range per lead for 100Ω, 1 kΩ ranges. 1 kΩ per lead on all other ranges.	
	Input Protection	1000 V on all ranges	
Measurement Method: Selectable 4-wire or 2-wire ohms. Current source referenced to LO input			
DC Current	Shunt Resistor	100Ω for 100uA, 1mA. 5Ω for 10mA and 100 mA. 0.1Ω for 1A. 0.01Ω for 10A.	
	Input Protection	Externally accessible 1.25A, 250 V fuse; Internal 12A, 600 V fuse	

Reading Rate (Readings/sec) [8]	Continuity/ Diode	Rate	Digits	Rate	
		Slow	6 ½	100	
		Mid	5 ½	200	
		Fast	4 ¼	300	
	DCV, DCI, 2W/4W Resistance	Rate	Digits	Accurate	Quick
		Slow	6 ½	5	30
		Mid	5 ½	60	600
		Fast	4 ¼	240	2400

[1] For DCV/DCI/ 2/4WR measurement modes, to reach specifications accuracy, must be set in accuracy speed, slow rate, A-Filter off, A-Gain on, A-Zero on.

[2] For Diode/CONT/TCO/RTD measurement modes, to reach specifications accuracy, must be set in slow rate, A-Gain on, A-Zero on.

[3] Relative to calibration standards.

[4] 20% overrange on all ranges, except 1000 Vdc and 10A range.

[5] Specifications are for 4-wire ohms function, or 2-wire ohms using REL

function. Without REL function, add 0.2 Ω additional error in 2-wire ohms function.

[6] 0˚C~18˚C, 28˚C~55˚C

[7] Accuracy specifications are for the voltage measured at the input terminals only. 1mA test current is typical. Variation in the current source will create some variation in the voltage drop across a diode junction.

[8] All speeds need A-Zero=off, A-Gain=off, Fixed range and Trigger Delay=0.

AC Characteristics [1]

True RMS AC Voltage [4]

Range[3]	Frequency	24 Hour [2] 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [9]
100.0000 mV	3Hz - 5Hz	1.00 + 0.03	1.00 + 0.04	1.00 + 0.04	0.100 + 0.004
	5Hz - 10Hz	0.35 + 0.03	0.35 + 0.04	0.35 + 0.04	0.035 + 0.004
	10Hz - 20kHz	0.04 + 0.03	0.05 + 0.04	0.06 + 0.04	0.005 + 0.004
	20kHz - 50kHz	0.10 + 0.05	0.11 + 0.05	0.12 + 0.05	0.011 + 0.005
	50kHz - 100kHz	0.55 + 0.08	0.60 + 0.08	0.60 + 0.08	0.060 + 0.008
	100kHz - 300kHz [6]	4.00 + 0.50	4.00 + 0.50	4.00 + 0.50	0.20 + 0.02
1.000000 V to 750.000 V	3Hz – 5Hz	1.00 + 0.02	1.00 + 0.03	1.00 + 0.03	0.100 + 0.003
	5Hz – 10Hz	0.35 + 0.02	0.35 + 0.03	0.35 + 0.03	0.035 + 0.003
	10Hz – 20kHz	0.04 + 0.02	0.05 + 0.03	0.06 + 0.03	0.005 + 0.003
	20kHz – 50kHz	0.10 + 0.04	0.11 + 0.05	0.12 + 0.05	0.011 + 0.005
	50kHz – 100kHz [5]	0.55 + 0.08	0.60 + 0.08	0.60 + 0.08	0.060 + 0.008
	100kHz – 300kHz [6]	4.00 + 0.50	4.00 + 0.50	4.00 + 0.50	0.20 + 0.02

Accuracy Specifications: ± (% of reading + % of range)

True RMS AC Current [4]

Range[3]	Frequency	24 Hour [2] 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [9]
1.000000 mA	3Hz – 5Hz	1.00 + 0.04	1.00 + 0.04	1.0+0.04	0.1+0.006
	5Hz – 10Hz	0.30 + 0.04	0.30 + 0.04	0.3+0.04	0.035+0.006
	10Hz – 5kHz	0.10 + 0.04	0.10 + 0.04	0.1+0.04	0.015+0.006
	5kHz – 10kHz	0.2 + 0.25	0.2 + 0.25	0.2+0.25	0.03+0.006

10.00000 mA	3Hz – 5Hz	1.1 + 0.06	1.1 + 0.06	1.1+0.06	0.2+0.006
	5Hz – 10Hz	0.35 + 0.06	0.35 + 0.06	0.35+0.06	0.1+0.006
	10Hz – 5kHz	0.15 + 0.06	0.15 + 0.06	0.15+0.06	0.015+0.006
	5kHz – 10kHz	0.35 + 0.7	0.35 + 0.7	0.35+0.7	0.03+0.006
100.0000 mA	3Hz – 5Hz	1.0 + 0.04	1.0 + 0.04	1.0+0.04	0.1+0.006
	5Hz – 10Hz	0.3 + 0.04	0.3 + 0.04	0.3+0.04	0.035+0.006
	10Hz – 5kHz	0.1 + 0.04	0.1 + 0.04	0.1+0.04	0.015+0.006
	5kHz – 10kHz	0.2 + 0.25	0.2 + 0.25	0.2+0.25	0.03 + 0.006
1.000000 A	3Hz – 5Hz	1.0 + 0.04	1.0 + 0.04	1.0+0.04	0.1+0.006
	5Hz – 10Hz	0.3 + 0.04	0.3 + 0.04	0.3+0.04	0.035+0.006
	10Hz – 5kHz	0.1 + 0.04	0.1 + 0.04	0.1+0.04	0.015+0.006
	5kHz – 10kHz	0.35 + 0.7	0.35 + 0.7	0.35+0.7	0.03 + 0.006
10.00000 A	3Hz – 5Hz	1.1 + 0.06	1.1 + 0.06	1.10 + 0.06	0.1+0.006
	5Hz – 10Hz	0.35 + 0.06	0.35 + 0.06	0.35 + 0.06	0.035 + 0.006
	10Hz – 5kHz	0.15 + 0.06	0.15 + 0.06	0.15 + 0.06	0.015 + 0.006
	5kHz – 10kHz	0.35 + 0.7	0.35 + 0.7	0.35+0.7	0.03 + 0.006

Accuracy Specifications: ± (% of reading + % of range)

Additional Crest Factor Errors (non-sine wave)[7]

Crest Factor	Error (% of reading)
1-2	0.05%
2-3	0.15%
3-4	0.30%
4-5	0.40%

Additional Low Frequency Errors(% of reading)

		AC Filter	
Frequency	Slow	Medium	Fast
10Hz~20Hz	0	0.74	-
20Hz~40Hz	0	0.22	-
40Hz~100Hz	0	0.06	0.73
100Hz~200Hz	0	0.01	0.22
200Hz~1kHz	0	0	0.18
>1kHz	0	0	0

Measuring Characteristics

True RMS AC Voltage	Measurement Method:	AC-coupled True RMS – measures the ac component of input with up to 400 Vdc of bias on any range.	
	Crest Factor	Maximum 5:1 at full scale	
AC Filter Bandwidth	Slow	3 Hz – 300 kHz	
	Medium	20 Hz – 300 kHz	
	Fast	200 Hz – 300 kHz	
	Input Impedance:	1 MΩ ± 2%, in parallel with 100 pF	
	Input Protection:	750 Vrms on all ranges	
True RMS AC Current	Range	Shunt	Burden Voltage
	1mA	100Ω	<0.15V
	10mA	5Ω	<0.07V
	100mA	5Ω	<0.7V
	1A	0.1Ω	<0.8V
	10A	10mΩ	<0.5V
	Input Protection:	Externally accessible 1.25A, 250 V fuse Internal 12A, 250 V fuse	

Operating Characteristics [8]

Function	Rate	Digits	Readings/s [10]	AC Bandwidth
ACV,ACI	Slow	6 ½	1.2 (sec/reading)	3 Hz – 300 kHz
	Medium	5 ½	3.38	20 Hz – 300 kHz
	Fast	4 ½	30	200 Hz – 300 kHz

[1] Specifications are for 1-hour warm-up at 6 1/2 digits, Slow ACfilter, sinewave input.

[2] Relative to calibration standards.

[3] 20% overrange on all ranges, except 750 Vac, 10A range.

[4] Specifications are for sinewave input >5% of range. For inputs from 1% to 5% of range and <50 kHz, add 0.1% of range additional error. For 50 kHz to 100 kHz, add 0.13% of range.

[5] 750 Vac range limited to 100 kHz

[6] Typically 30% of reading error at 1 MHz.

[7] For frequencies below 100 Hz, slow AC filter specified for sinewave input only.

[8] Additional settling delay required when input dc level varies.

[9] 0˚C~18˚C, 28˚C~55˚C

[10] All speeds need Fixed range and Trigger Delay=0.

Frequency and Period Characteristics

Frequency Period [3] [7]

Range [2]	Frequency	24 Hour [1] 23˚C±1˚C	90 Day 23˚C±5˚C	1 Year 23˚C±5˚C	Temperature Coefficient/˚C [5]
100 mV to 750 V [4]	3Hz - 5Hz	0.1	0.1	0.1	0.005
	5Hz - 10Hz	0.05	0.05	0.05	0.005
	10Hz - 40Hz	0.03	0.03	0.03	0.001
	40Hz - 300kHz	0.006	0.01	0.01	0.001

Accuracy Specifications: ± % of reading

Measuring Characteristics

Frequency and Period	Measurement Method:	Reciprocal-counting technique. AC-coupled input using the ac voltage measurement function.
	Voltage Ranges	100 mVrms full scale to 750 Vrms. Auto or manual ranging.
Settling Considerations	Errors will occur when attempting to measure the frequency or period of an input following a dc offset voltage change. The input blocking RC time constant must be allowed to fully settle (up to 1 sec) before the most accurate measurements are possible.	
Measurement Considerations	All frequency counters are susceptible to error when measuring low-voltage, low-frequency signals. Shielding inputs from external noise pickup is critical for minimizing measurement errors.	

Operating Characteristics

Function	Digits	Readings/s [6]
Frequency, Period	6 ½	1
	5 ½	10
	4 ½	100

[1] Relative to calibration standards.

[2] 20% overrange on all ranges, except 750 Vac.

[3] Input > 100 mV. For 10 mV to 100 mV inputs, multiply % of reading error x10.

[4] 750 Vac range limited to 100 kHz

[5] 0˚~18˚C & 28˚~55˚C

[6] Need Fixed ACI/ACV range and Trigger Delay=0.

[7] To meet the specifications accuracy, *Slow rate* setting is needed.

Temperature Characteristics

(Display in °C, °F, Exclusive of probe errors.)

RTD [1] (Accuracy based on PT100):

(100Ω platinum [PT100], D100, F100,PT385, PT3916, or user type)

Range	Resolution	1 Year (23°C ±5°C)	Temperature Coefficient 0°-18°C & 28°-55°C
-200°C~ -100°C	0.001°C	0.09°C	0.004 °C / °C
-100°C~-20°C	0.001°C	0.08°C	0.005 °C / °C
-20°C~20°C	0.001°C	0.06°C	0.005 °C / °C
20°C~100 °C	0.001°C	0.08°C	0.005 °C / °C
100°C~300 °C	0.001°C	0.12°C	0.007 °C / °C
300°C~600 °C	0.001°C	0.22°C	0.009 °C / °C

Thermocouples [1] (Accuracy based on ITS-90):

Type	Range	Resolution	90 Day/1 Year (23°C±5°C)*	Temperature Coefficient 0°-18°C & 28°-55°C
E	-200 to +1000°C	0.002 °C	0.2 °C	0.03 °C / °C
J	-210 to +1200˚C	0.002 °C	0.2 °C	0.03 °C / °C
T	-200 to +400°C	0.002 °C	0.3 °C	0.04 °C / °C
K	-200 to +1372˚C	0.002 °C	0.3 °C	0.04 °C / °C
N	-200 to +1300˚C	0.003 °C	0.4 °C	0.05 °C / °C
R	-50 to +1768˚C	0.01 °C	1 °C	0.14 °C / °C
S	-50 to +1768˚C	0.01 °C	1 °C	0.14 °C / °C
B	+350 to +1820˚C	0.01 °C	1 °C	0.14 °C / °C

*Relative to simulated junction

Reading Rate [2] (Readings/sec) TCO/ RTD			
Rate	Digits	Rate	
Slow	6 ½	10	
Mid	5 ½	60	
Fast	4 ¼	300	

[1] Specifications do not include probe accuracy

[2] All speeds need A-Zero=off, A-Gain=off, Fixed range and Trigger Delay=0.

Dimensions



All dimensions are shown in millimeters.

EC Declaration of Conformity

We
GOOD WILL INSTRUMENT CO., LTD.
(1) No.7-1, Jhongsing Rd., Tucheng Dist., New Taipei City, Taiwan (R.O.C.)
(2) No. 69, Lu San Road, Suzhou City (Xin Qu), Jiangsu Sheng, China
declare, that the below mentioned product

Type of Product: **Digital Multimeter**
Model Number: **GDM-8261A**

are herewith confirmed to comply with the requirements set out in the Council Directive on the Approximation of the Law of Member States relating to Electromagnetic Compatibility (2004/108/EC) and Low Voltage Directive (2006/95/EC).
For the evaluation regarding the Electromagnetic Compatibility and Low Voltage Directive, the following standards were applied:

◎ EMC

EN 61326-1: EN 61326-2-1:	Electrical equipment for measurement, control and laboratory use — EMC requirements (2006)
Conducted & Radiated Emission EN 55011: 2009+A1:2010	Electrostatic Discharge EN 61000-4-2: 2009
Current Harmonics EN 61000-3-2: 2006 +A1:2009+A2:2009	Radiated Immunity EN 61000-4-3: 2006 +A1:2008+A2:2010
Voltage Fluctuations EN 61000-3-3: 2008	Electrical Fast Transients EN 61000-4-4: 2004+A1:2010
----------	Surge Immunity EN 61000-4-5: 2006
----------	Conducted Susceptibility EN 61000-4-6: 2009
----------	Power Frequency Magnetic Field EN 61000-4-8: 2010
----------	Voltage Dip/ Interruption EN 61000-4-11: 2004

◎ Safety

Low Voltage Equipment Directive 2006/95/EC
Safety Requirements EN 61010-1: 2010 EN 61010-2-030 : 2010

INDEX

A

AC bandwidth
  setting 86
ADC speed
  setting 92
Analog filter
  setting 82
Auto-gain
  setting 90
Auto-zero
  setting 88

B

Beeper
  setting 40

C

Command IEE488.2 commands 203
Command set
  CALCulate commands 194
  CONFigure commands 172
  CONFigure2 commands 174
  Measure commands 177
  Remote commands 203
  ROUTe commands 205
  SENSe commands 180
  STATus report commands 203
  SYSTem related commands 200
  TRIGger commands 197
Command syntax
  configuration
    EOL 135
    return format 136
    separation character 136
  overview 163
Compare value
  setting 65
Continuity
  setting 38
Crest factor 31
Current
  scanner configuration 105
  setting 32
Current auto-detect
  input port setting 87

D

dB
  setting 58
Digital filter
  setting 79
  window 80
Digital I/O
  Compare application 125
  configuration 124
  External trigger application 128
Diode test
  scanner configuration 105
  setting 37
Disposal instructions 8
D-Shift
  setting 84
Dual measurement
  applications 49
  operation 51
  overview 49

E

EN 55011 declaration of conformity 227
EN 61010
  declaration of conformity 227
  measurement category 7
  pollution degree 8
Environment
  operation 8
  storage 8
Ethernet configuration
  activation 142
  DHCP 145
  DNS 151

Gateway 149
Initial settings 154
IP 146
MAC address 152
Reset 144
Subnet 148
Telnet 153
Web password 156
Ethernet installation 141

F

FAQ 209
Firmware version 212
Frequency
scanner configuration 105
setting 41
Frequency/period
gate time setting 95
input port setting 93
Front panel
overview 12
Fuse
AC fuse replacement 213
current fuse replacement 214
safety instruction 8

G

Getting Started chapter 10
GPIB configuration 139
GPIB installation 138

I

Indicator
reading 26
Input resistance
setting 85

L

LAN installation 141
LANG
setting 96
Line voltage safety instruction 7

M

Main features 11
Math
1/X 70
MX+B 68
Percentage 70
setting 68
Standard deviation 71
Statisics 71
Measurement keys
overview 13
Menu tree 215
Monitor channel 121

P

Period
scanner configuration 105
setting 41

R

Rear panel
overview 18
Recall instrument settings 101
Recall measurements 99
Refresh rate 25, 56
Refresh rate
setting 75
Relative value
setting 62
Remote terminal session
telnet 157
Resistance
scanner configuration 105
setting 34
RS-232C configuration 133

S

Safety instruction
fuse 8
Line voltage 7
symbol 6
Save instrument settings 100
Save parameters 100
Scanner
advanced settings 116
command set 205
get out of scanner mode 209
installation 104
Overview 113
run scan 120
simple settings 114
step operation 120

triggering 119
Scanner configuration record/log 112
Serial number
setting 75
Service contact 210
Specification conditions 209
Specifications
AC
characteristics 221
measuring chacteristics 223
Operating characteristics 223
DC
characteristics 219
measuring characteristics 220
Dimensions 226
Frequency and Period
characteristics 224
measuring characteristics 224
Operating characteristics 224
General 218
Temperature characteristics 225
Status system 217
Store measurements 98

T

Table of contents 3
Temperature
RTD setting 47
scanner configuration 105
setting 43, 46
Thermocouple
junction setting 45
setting 44
Tilt stand 20
Trigger
delay 78
external 76

U

United Kingdom power cord 9
USB configuration 132

V

Voltage
scanner configuration 105
setting 27

W

W
setting 58
Waveform type voltage comparison 30
Web control
overview 159
Web control interface 159